EXHIBIT 5[UNREDACTED VERSION OF DOCUMENT SOUGHT TO BE SEALED]



Grenada/Bacall BP2 CTU and Grenada SAD Approval Request 1/15/14

Grenada Core Team Seagate Technology



Grenada/Bacall BP2 Core Team Requests Your Approval

At this time the Grenada/Bacall BP2 Core Team is requesting your approval for CTU shipments for Grenada and Bacall BP2. In addition we are requesting Grenada BP2 SAD. Metrics for these requests have been meet with no exceptions. Factory team is preparing a ramp plan for Q3 and will be used to update MBS.

CTU's will include Plastic DSP and TI Dillon servo ASIC. This is for CTU only at this time and the usage of those parts in revenue shipments require a regression qualification to ensure we meet cleanliness, yield and Reliability metrics for volume release configurations.

- •Plastic DSP's will require a improved cleanliness of the part via gate treatments and/or FOF cleaning. Expected timelines for HiP are by end of Q3
- •TI Dillon needs a new wire frame to eliminate shorting seen in board assembly, updated firmware and BOM to resolve yield issues seen at board test, factory drive yields, and other program experience with TI Dillon. Expected timelines for TI Dillon regression are by end of Q3.
- •500GB one headed builds will require new machining changes to ensure we maintain RSA/PSA targets for Grenada builds. RGA and ODT testing close out qualification by Feb, Thanit working to pull in earlier.
- •Lombard "new2" clamps for plug balance will be phased in once regression testing completes end of January. This will remove restriction of using TDK parts on Bacall MD drives. CRT2 has started and should complete ~2/20 and will be utilized to achieve SAD for Bacall BP2

and serve as a visible RDT for OEM's which require for RTS. Scrap/Yield plans are included for uPemto and GOTF differences which the Core Team will close along with Factory and RHO.

If you have any questions or concerns please contact the Grenada/Bacall BP2 Core Team! Go Grenada/Bacall BP2!



Case 3:16-BP22CTCU/SADerDeclare-Checklistge 4 of 128

7. CTU/SAD Product: Grenada/BacallBP2

		Report Date:		1/15/2014		
Inctional Organization	Deliverables	Criteria	Last Update	Current Status	Risk	Owner
	10 May 17 10 May		<u> </u>	I co		
Phase Exit Milestone Criteria	Yields and Test Times meet Phase 0 Targets	PARTY.	1/15/2014		No Risk Assigned	
		8K	1/15/2014		No Risk Assigned	
	All contract items are within variance and projected to remain so	Yes	1/15/2014	Yes	No Risk Assigned	
	Compare CC/SKU Count Matrix with approved Phase 0 Contract. Highlight differences to the SMT.		1/15/2014	Yes	No Risk Assigned	
		SSP sources approved to AML level AB with underpinned closure plans.	1/15/2014	Underpinned	Low Risk	Materials/Bob Kolanda and Core Team
	Contamination Management Plan			Yes	No Risk Assigned	
	Design Engineering Checklists Complete: Mech, Servo, El, HDIG/ RSS, Firmware, RHMO	Complete	1/15/2014	Yes	No Risk Assigned	
	DMT Criteria Met	Complete	1/15/2014	Yes	No Risk Assigned	
	Exceptions to previous Phase Review closed	None	1/15/2014	Yes	No Risk Assigned	
	Head Electrical Test Yields meet Phase 0 Targets	Complete (89.2%)	1/15/2014	Yes	No Risk Assigned	
	Integration DPPM Goal Achieved	1K criteria	749	Yes	No Risk Assigned	
	Inventory / Material Disposition - Complete roll-up of all Factory and DC pre-SAD config inventory/WIP/FG and Disposition	Complete roll up and disporition		Yes, this is managed weekly by Bob Kolanda and Core team	No Risk Assigned	
	MTBF Achieved	250/400K MTBF	1/15/2014	268/481K MTBF	No Risk Assigned	
	No High Risk Issues	No high risk items	1/15/2014	Yes	No Risk Assigned	
	 All testing applies PDP Deliverables completed and entered into PDR database. 	In Progress	1/15/2014	In progress	Low Risk	
	100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Complete	1/15/2014	Not Posted	No Risk Assigned	
	 Includes QA Hardware/Software Readiness Includes Rework Qualification Plan in place with 					
	closure by SAD.					
	Product Stewardship Declaration of Complance at a minimum of 95% completed.		1/15/2014		No Risk Assigned	
	Testing Complete - Product Assurance, Firmware/Compatibility & Engineering Regression	Complete	1/15/2014	Yes	No Risk Assigned	

case BOMstorsGrenada/BacalleCeTUage 5 of 128

Product Segment Alignment

•BP2 Grenada/Bacall 1,2-3D Disty and OEM

Mechanical

- •Media any approved BP1.5, Showa will be added upon completion of qual.
- •Common BOM items Mostly BP1.5, include 430SST TC, Plastic DSP from HiP for CTU only, no mass production until regression RDT demo with cleaner gate changes!
- •MBA Nidec, Semco (Option1,2,and3)
- ·Stack Assy Kaifa, Korat, Wuxi
- •Preamp TI, LSI 2-4-6ch. No fab exclusions
- •PCC / PCCA / Hookup Approved base can support MS demand, full closure in CRT2
- Head / Wafer Native / Consign uPemto (bar bake, IR PZT cure, with CA wafer!)
- •TGA MPT/NHK 11.3.1 or 4.7 MPT for Consign

Electrical

- •GBP32 Dillon ST, TI Assy can be used for CTU, no mass production until we regress configuration and demo yield parity, no assy subcon exclusions
- •SOC LSI Luxor Lite, no Fab or packaging site restrictions
- •SVO Dillon ST, Dillon TI for CTU only
- •Flash Winbond, Sanyo, no Elite
- •DDR Winbond, Samsung, Nanya, Hynix

Firmware/PCO

•PCO >/= 4.3 and code as defined on BOM's





Product Segment Alignment

•BP2 Grenada 1,2-3D Disty and OEM

Mechanical

- •Media any approved BP1.5, Showa will be added upon completion of qual.
- •Common BOM items Mostly BP1.5, include 430SST TC, No Plastic DSP from either vendor until regression RDT demo with clean gate changes
- •MBA Nidec, Semco (Option1,2,and3)
- ·Stack Assy Kaifa, Korat, Wuxi
- •Preamp TI, LSI 2-4-6ch. No fab exclusions
- •PCC / PCCA / Hookup Approved base can support MS demand, full closure in CRT2
- Head / Wafer Native / Consign uPemto (bar bake, IR PZT cure, with CA wafer!)
- •TGA MPT/NHK 11.3.1 or 4.7 MPT for Consign

Electrical

- •GBP32 Dillon ST No TI Assy until we regress configuration and demo yield parity, no assy subcon exclusions
- •SOC LSI Luxor Lite, no Fab or packaging site restrictions
- •SVO Dillon ST, no Dillon TI until we regress configuration and demo yield parity
- •Flash Winbond, Sanyo, no Elite
- •DDR Winbond, Samsung, Nanya, Hynix

Firmware/PCO

•PCO >/= 4.3 and code as defined on BOM's






BP2 T315 instability failures action plan

- PCO5.0
 - PCO 5.0 will be delivered to factory for check out and RGA on 02/6/2014
 - This PCO will have enhanced instability grading
 - This grading will contain additional checks for degradation (delta BER in T250) and instability (T297)
 - Expect 30-40% recovery in yield over PCO4.3
- From PCO 5 RGA, recommend collection of residual failures (n=100 minimum) for 500 hr run RDT
 - Korat Reliability to make call regarding quality of this failing sliver

GrenadaMP/GremadaBP2m9/15/eri@Y12/18Optlook (12A)



Wailnn Choong

	Grenada BP2 Yield Improvement Plan Itemization									S6+)
Category	FW	Date	Yield Adjustment Item	Impacted CTQ	Budgeted BER Change (QMON0)	Budgeted ADC change	Sort Yld (Prime)	Drive ADC mean (S5+)	Sort Yld (S5+)	Sort Yld (S6+)
Current baseline	1350	6/13/13	BP4.5 Transducer (M9/HMRB9.6/22A DLC/G8.5B+)				72	1.03	84	82
uPemto/dPemto offset	1351		ADC/BER retest aligned to dPemto	BER/ADC	-0.05	0.8%	74	1.04	84	82
closure	1352		Q413 Reader res delta FA and corrective actions	Yield	0.00	0.0%	76	1.04	86	83
Closule	1410		HFA gradient improvement	Stability / HFA Sigma	0.00	0.0%	77	1.04	87	84
Head	1405		ADC TF/spec opti	ADC	0.00	0.0%	78	1.04	88	85
Head	1405		WPE target to 3.25µin	WPE mean	-0.14	2%	79	1.04	89	86
Head	1413		Stability open spec build with current AAB	Stability	0.00	0.0%	81	1.04	91	89
Drive	1415	10/11/13	BP2 drive system gain	Drive ADC	0.00	3%	81	1.07	91	89
Head	1423	12/6/13	Stability open spec build with low flying AAB	Stability	0.00	0.0%	82	1.07	92	89
Media	1426	12/27/13	Grenada G9.1LT Media	BER/ADC/OVW	-0.20	3.0%	85	1.10	93	91
Head	1427	1/3/14	uGBP8 Transducer (Wafer TBD, Fairlane 1.0, Carraig2A, Exc1.0, LB Opti1)	BER/ADC; Stability	-0.13	2.0%	87	1.12	94	92
Future opportunities	1501	7/5/14	BP9 Transducer (EXC3.1)	BER/ADC/OVW	-0.15	2.3%	89	1.15	95	92

- Baseline Yields change to 72% Native 84% Cum
- Changes from FW45 YIP:
 - Offset Closure increases cum yield from 85 to 87
 - At 1.05/1.06 next phase of drive open specs due to ADC maturity
 - Revise timeline ADC TF Opti / Stability open spec build

Seagate Confidential (#)

Slider Base 11 16 Page 10 of 128

STPG

Baseline 2.7b = BL 2.7 with the addition of

- Modified AKL carrier (MCD II)
- Talc-Free PU Tape at carrier mount for dice

Modular Carrier Design – MCD II

- Poor stripe height control of uPemto bar ends with original carriers (uPemto bar ends extend beyond last finger on carrier).
- Internal carrier component re-design: increase width of three end fingers, enabling better push/pull stroke on these fingers, and hence delivering better SH and flatness control of bar-end sliders.
- No change or impact to any other bar dimensions or AKL targets.
- RGA/ Full Implementation: FW41 47


Talc-Free PU Tape

- Previous Polyurethane (PU) tape was the primary source of talc (MgSiO) particles.
- The use of Talc-Free PU tape needed 5-deg increase in HBTC and oven temperatures (110C to 115C) to achieve the required adhesion for dicing.
- RGA/ Full Implementation: FW38 44


311 3
BL2.7b
PDI Baseline
GF=500/800
3+2
11.22.e064_SAW1
PEEK Weight
Reverse Glazing
Ambient Cooling
Shielded
H&K 1mil Norm 64
3M (1um)
225nm
200um-V, CB15
5% 10min soak
2x ring, 5min
L6037+Oxidant
FAPC
30% 70nm emuls.
ANAC buff
V-Mount
Chamfer Gel
fodular Carrier (MCD II)
68 end Lr (Alt bond)
3.7
AKL3.4 iPC
normal oscill.
Final Hi
STKL-1097
900A + Shift FAWS (new clamper)
FAWS (new clamper)
IRC IPA
Solvent Tooltek
UV Ozone
No Scrubber
Pre DLC SSEC IPA
No Scrubber Pre DLC SSEC IPA PLS2
500.04 UCJ1
Gen0/1
55+75, 150
Optimized photo
3% MD
Acetone Wipe
Acetone Ultrasonic
Rcp2
Talc Free PU Tape II
2x
Yes
SSEC
Ceramic Insert
New Spacer 3-hr Rest Time Infinity
3-hr Rest Time Infinity
Sonic
3%
Recipe 2.5

Seagate Confidential


Grenada u - 155-5 Filed 01/12/18 Page 11 of 128



Grenada BP2 / uPemto (CYP as of WW51'13)	When	Expect Gain	Cum ET Yield	Confidential leve
Base line			84.0%	
ADC/BER retest aligned to dPemto	FW1352	0.0%	84.0%	
Q413 Reader Res Delta FA & CA	FW1402	1.0%	85.0%	
ADC TF and spec optimization	FW1405	0.0%	85.0%	
WPE target to 3.25u	FW1405	0.0%	85.0%	
HFA gradient improvement	FW1410	1.0%	86.0%	
Stability Open Spec with current AAB	FW1413	2.0%	88.0%	
Stability Open Spec with low flying AAB	FW1423	1.0%	89.0%	
G9.1LT Media	FW1426	1.0%	90.0%	
PDP SAD+4	FW1438	0.0%	90.0%	
uGBP8 Transducer (Fairlane1.1, NSS7, Carraig2A, EXC1.0, LB Opti1)	FW1439	1.0%	91.0%	
BP9 Transducer (EXC3.1)	FW1501	1.0%	92.0%	
PDP SAD+10	FW1509	0.0%	92.0%	
PDP SAD+13	FW1522	1.0%	93.0%	
PDP SAD+16	FW1535	2.0%	95.0%	
PDP SAD+19	FW1548	0.0%	95.0%	
PDP SAD+22	FW1609	0.0%	95.0%	



Remark: Consider all Green as Pre-lim.



Recipe 3.1 Update



Penang Slider Operations

Next Potential improvement 155-5 Filed 01/18/18 Page 13 of 128

NRM and Penang Cleaning Team collaboration

Changes to affect

- Removal of Cyanoacrylate residuals with micro90 wipe → Nano contam
- Full immersion cleaning upstream → Sidepad/backpad cleanliness
- Lower 192kHz power → Nano Pitting
- Elimination of non-value add steps

Cleanliness results to date look very good.

Changes to flow and chemistry are significant and require interactions assessment. (in progress)

Implementation targeted for Sept 2013


Seagate Confidential #

uPemto PROCESS BL2.7B Cleaning (POR BASELINE) BL3.1a + Hybrid Tray Case 3:16-cv-0052B20@BV45 Doctument 155-5 Filed 01/412/108 Page 14 of 128 BL3.1a Wafer Grip Wax AQ SSEC AQ SSEC OSL PAWS PAWS AKL Modular Carrier II Modular Carrier II Chamfer Gel Pack FAWS **FAWS IPAIRC IPAIRC** Solvent Tooltek Solvent Tooltek AQ SSEC AQ SSEC (PreDLC nano) (FastScan I) IPA SSEC IPA SSEC <FastScan II> UVO UVO DLC Free Sorubber Sorubber Cyano-acrylate PreCoat IRC PreCoat IRC AAB Resist Strip IRC x 3 Resist Strip IRC x 3 SCBD (Acetone Infinity) SCBD (Acetone Infinity) <FastScan III> BackPad Acetone Wipe Microposit + BackPad Acetone Wipe nano contam, cyanoacrylate Free (FastScan IV) Acetone Infinity Acetone Infinity HMR. IPA IRC HBTC IPA IRC HBTC Talo Free PU Tape Talo Free PU Tape DICE Post Dice 192kHz (11/2 Chemcrest, 200W/gal, 20mil Post Dice 192kHz (11/4 Chemorest, 100W/gal, 10min) nano pits PUTape IPA-SSEC IPA SSEC **IPAIRC** <SAVI> DEB Post DEB 192kHz (1% Chemorest, 200W/gal, 20mir Post Dice 192kHz (1% Chemcrest, 100W/gal, 10min) nano pits IPA SSEC IPA-SSEC **IPAIRC KSAVI** Infinity Soak (ceramic w/sonics) Infinity Soak (ceramic w/ultrasonic) investigate no sonic ATS - C&S Trays Lubrizol (flat) Lubrizol (flat) SA Prime (Acetone, 250s, <120F) 1st 192kHz (31/2 Valtron, 12min) Auto 192kHz (Vertical) <100x, 30x, 30x QA> Kerry Mk 4 Kerry Mk4 < 30x SPI, 30x, 30x QA > Pre Tooltek (Valtron, 3x rinse) Pre Tooltek (Valtron, 30 rinse) < 100x> DFF (4s, 100% 200x LE, N=100 Post Tooltek (Valtron, 3 rinse cycles) Post Tooltek (Valtron, 3 rinse cycles)

Clean & Ship Trays SA Prime (Acetone, 250s, <120F) SA Prime (Acetone, 250s, <120F) Optimag, SFAVI, 100x IPQA Auto 192kHz (11/2 Valtron, 6min/tank, tripre 1) Auto 192kHz (11/2 Valtron, 6min/tank, trince †) <SFAVI, IPQA 100x> Seagate Confidential SA Prime (Acetone, 250s, <120F) SA Prime (Acetone, 250s, <120F) OBA, OBA nano >< FastScan \ FED SEAG0057289

HIGHLY CONFIDENTIAL

dPemto: Sinder Nano Contam Performance



Summary (for product with Recipe 2.6a): Recipe# 2.6a

Mode 0 Mode 0 + Light	Baseline 16% 87%	Implementation 23% 87%	•
S/Size		214pcs	•

In summary, recipe 2.6a is significantly better in terms of mode 0, 24% post cut in vs recipe 2.5 baseline of 16%.

Recipe 2.6a implemented on 11-Apr-13. Data collection ongoing.


100% recipe 2.6a started from early FW43'13 @ slider outgoing.

ETB (recipe 3-1) ongoing and prelim data showing positive results. ETB Group 2 expected HGA results end of this week.

Seagate Confidential

HIGHLY CONFIDENTIAL


dPemto: Outgoing Pole Taic



- Big clean post talc free PU tape implementation completed in early of FW48'13. Data from FW49'13 onwards showing 100% type ND + type I.
- Continue to monitor the data.

Seagate Confidential (#)


uPemto: Sinder Nano Contam Performance



- Recipe 2.6a has comparable or better performance in terms of nano contam for uPemto. Slider cut in on end of FW46'13.
- Slider marking started on 27-May-13. All marked as '26A' on 2x2 label.
- Big clean post talc free PU tape implementation completed in early of FW48'13.

Seagate Confidential #5


uPemto: Outgoing Pole Taic



- Big clean post talc free PU tape implementation completed in early FW48'13. Data from FW49'13 onwards showing 100% type ND + type I.
- Continue to monitor the data.

Seagate Confidential (#)

ETB Eval: incoming HGA Nano Contam Level



- HGA incoming is observing the similar good performance as slider OBA. Continue to build more small sample size eval to validate this gain.
- 2nd pc of data expected end of FW51'13.

Courtesy: Kiattisak S

and Tanut P

Seagate Confidential (#)

ETB2: Slider fin Process and Outgoing Performance

Observed gain in 100x optical inspection

in terms of contam yield loss.

M8RHO			ĺ							
	30)	(SPI	100x Ins	pection	SFAVI		OBA (Co	ontam)	OBA (Overall)	
Group	QTY	SPI %	Qty	Contam %	Qty	Contam %	Qty	Contam DPPM	Qty	Overal DPPM
ETB1	1000	0	8117	0.80	3750	1.5	250	0	250	0
ETB2			13186	0.77	13072	2.3				
Eval Average (ETB)	1000	0	21303	0.79	16822	1.9	250	0	250	0
Control (Baseline)		2-3%	1564194	1.4	540544	0.9	13900	1726	13900	3591
Delta (Ctrl - Eval) (ETB)			1542891	0.62	523722	-1.0	13650	1726	13650	3591

Control data taken from FW46 onwards

Megalodon					1					
	30)	(SPI	100x Inspection		SFAVI		OBA (Contam)		OBA (Overall)	
Group	QTY	SPI 96	Qty	Contam %	Qty	Contam %	Qty	Contam DPPM	Qty	Overal DPPM
ETB2	1800	0	16341	0.4	16255	0.83	500	2000	500	4000
Eval Average (ETB)	1800	0	16341	0.4	16255	0.83	500	2000	500	4000
Control (Baseline)		2-3%	4884890	1.89	471348	3.41			81500	3524
Delta (Ctrl - Eval) (ETB)			4868549	1.49	455093	2.58			81000	-476

Control data taken from FW46 onwards

GrenadaMP2/M8BP2

30)	(SPI	100x Inspection		SFA	AVI	OBA (C	ontam)	OBA (Overall)		
QTY SPI% Qty Contam		Qty	Contam %	Qty	Contam DPPM	Qty	Overal DPPM			
400	0	4026	0.25	3640	0.7	250	0	250	0	
1500	0	7613	0.28	7525	1.8	250	4000	250	8000	
1900	0	11639	0.265	11165	1.25	500	2000	500	4000	
	2-3%	501562	2.0	454123	2.0	8000	1250	8000	3125	
		489923	1.735	442958	0.75	7500	-750	7500	-875	
	QTY 400 1500	400 0 1500 0 1900 0	QTY SPI% Qty 400 0 4026 1500 0 7613 1900 0 11639 2-3% 501562	QTY SPI% Qty Contam % 400 0 4026 0.25 1500 0 7613 0.28 1900 0 11639 0.265 2-3% 501562 2.0	QTY SPI% Qty Contam % Qty 400 0 4026 0.25 3640 1500 0 7613 0.28 7525 1900 0 11639 0.265 11165 2-3% 501562 2.0 454123	QTY SPI% Qty Contam % Qty Contam % 400 0 4026 0.25 3640 0.7 1500 0 7613 0.28 7525 1.8 1900 0 11639 0.265 11165 1.25 2-3% 501562 2.0 454123 2.0	QTY SP1% Qty Contam % Qty Contam % Qty Contam % Qty 400 0 4026 0.25 3640 0.7 250 1500 0 7613 0.28 7525 1.8 250 1900 0 11639 0.265 11165 1.25 500 2-3% 501562 2.0 454123 2.0 8000	QTY SPI% Qty Contam % Qty Contam % Qty Contam DPPM 400 0 4026 0.25 3640 0.7 250 0 1500 0 7613 0.28 7525 1.8 250 4000 1900 0 11639 0.265 11165 1.25 500 2000 2-3% 501562 2.0 454123 2.0 8000 1250	QTY SP1% Qty Contam % Qty Contam % Qty Contam DPPM Qty 400 0 4026 0.25 3640 0.7 250 0 250 1500 0 7613 0.28 7525 1.8 250 4000 250 1900 0 11639 0.265 11165 1.25 500 2000 500 2-3% 501562 2.0 454123 2.0 8000 1250 8000	

Control data taken from FW46 onwards

OBA - ETB Package uPemto M8BP2

	Lot Id	OBA QA 100X							
No	Lot Id	Sample Size	Qty Rej	Defect Type					
1	O2EI33CN	50	0	0					
2	O2EI2UCK	50	0	0					
3	O2EI2RBY	50	1	pid (r4,c1)					
4	O2EHYWC2	50	1	cont abs (r12,c4)					
5	O2EI2QCD	50	0	0					
	TOTAL	250	2						

8000

Next Steps Case 3:16-cv-00523-JCS Document 155-5 Filed 01/12/18 Page 21 of 128

Q1'14: (Recipe3.1a)

- Low power manual 192kHz (WW09) (new)
- IPA IRC for Dice/DEB
- Microposit back pad wiping post SCBD (WW09) (new)
- Auto192kHz Vertical tank at post Sort & ABS Inspect (WW09-data for decision)
- 1st SA at post Sort (per original 3.1)
- Eliminate 1st Tooltek (per original 3.1)
- Auto192kHz moved to pre ABS Inspect with SA solvent clean as last operation (new)

Q2'14 (Oct'13): Recipe 3.2

- IRC Cyclohexane to replace IRC IPA at HMR & DEB (100k Sept, Oct implementation)
- No sonic at Slider Dismount for uPemto (ceramic s/block) (WW16)
- Post dice/DEB manual 192khz elimination for complexity reduction
- Modification or chemistry/rinse for manual 192kHz
- Micro90 Aq Tooltek

Q3/Q4'14: (BIC Process) BIC Recipe Demo

- Solvent sonic brush (post SCBD, post ATS, final clean)
- Solvent emersion brush (post SCBD, post ATS, final clean)
- Aqueous sonic brush (post SCBD, post dice/DEB, EOL clean)

Seagate Confidential (#)

Grenada BP216C1101/SAD Disty/OEM

Page 22 of 128

Product Name: Grenada BP2 Approval Date: January, 15, 2014

Design Center: LCO Goal: Authorizes CTU's and Volume Shipments to Disty and OEM

Volume Factory: Korat, Wuxi, Suzhou Configuration: .5,1,2,3TB

Design Center Approval:

Pat Dewey
Pat Dewey

Grenada BP2 Core Team Exec I

Brent Vandervliet
Brent VanDerVliet

Exec Dir Prd Eng

Glen Almgren

Glen Almgren Director, CEE Mike Kepler

Mike Kepler
Exec Dir Materials

Suzette Simonich

Suzette Simonich

Director, Prod Mktg

Mike Foye

Mike Foye

Ex Dir, TCM

Val LaRoche CW

Val LaRoche Sr. Dir Finance

Drive Ops Factory
Site Lead VP

Piangruetai Sivaratana

Jeff Mason

Jeff Mason

VP Design Engineering

Exceptions Approval for CTU/ SAD NA

Mark Re SVP, CTO John Grieci SVP, Cust Advocacy & Prod Mktg Kian Fatt Chong
SVP, Drive Asia Ops

Grenada BP2
Retail SAD Ship Approval Document
November 22, 2013

© Seagate Confidential

Bacall BP2asCttu-00523-1Cs Disty/OEM

Filed 01/12/18 Page 23 of 128

Product Name: Bacall BP2 Approval Date: January, 15, 2014

Design Center: LCO Goal: Authorizes CTU's Shipments to Disty and OEM

Volume Factory: Korat, Wuxi, Suzhou Configuration: 1,2,3TB

Design Center Approval:

Pat Dewey
Pat Dewey

Grenada BP2 Core Team

Brent Vandervliet

Brent VanDerVliet Exec Dir Prd Eng Glen Almgren

Glen Almgren
Director, CEE

Mike Kepler

Mike Kepler
Exec Dir Materials

Suzette Simonich

Suzette Simonich

Director, Prod Mktg

Mike Foye

Mike Foye

Ex Dir, TCM

Val LaRoche CW

Val LaRoche

Sr. Dir Finance

Piangruetai Sivaratana Drive Ops Factory

Site Lead VP

Jeff Mason

Jeff Mason

VP Design Engineering

Exceptions Approval for CTU:NA

Mark Re SVP, CTO John Grieci SVP, Cust Advocacy & Prod Mktg Kian Fatt Chong
SVP, Drive Asia Ops

Grenada BP2
Retail SAD Ship Approval Document
November 22, 2013

© Seagate Confidential

Plastic DSP Gate Update


Seagate (C)

January 15, 2014

Steve Martin, John Alonzo, Katrina Killough, Joanne Larson, Chris Dion, Sonia Marrero, Rick Rupp, James Dunckley, Greg Schultz, Lori Antolec



SEM Directonspections Hippoplastic PSP2s for Grenada BP – Gate Region



Problem: Manually degated plastic DSPs pose significant particle risk.

Au-coated 1.0kV 9.5mm x30 SE(M) 12/5/2013

Strategy: Modify gate surface condition to mitigate risk.

SEM images: Katrina Killough, Joanne Larson

Au-coated 1.0kV 9.5mm x200 SE(M) 12/5/2013


Gate Improvement Options


Process	Gate Condition	Initial LPC (0.3um, 68kHz)	Process Maturity / UPH	Comments
Manual Degate Only	Fully Exposed	Pass	Excellent	
Manual Degate + Hot Seal	> 90% sealed	Pass	Very Good	
Manual Degate + Epoxy coating	~100% sealed	Pass	Fair	Outgassing risk & Poor dimensional capability so far
Manual Degate + Ultrasonic Welding	? (unknown)	? (unknown)	Fair	Update by Jan 21

- Hot Seal is primary path. Other options that will continue to be tracked are adhesive coating and ultrasonic welding.
- HiP preparing 2000 pc. Cavity 3 with <u>Hot Seal</u> method, target to be in Korat by end of WW 30.

Hot Seal Assembly







Temperature controller set at required sealing temperature

Part located on the movable fixture Activate Pneumatic Cylinder to perform the hot sealing process Part on the movable fixture will be pressed against the hot seal at the gate area The movable fixture will be moved away from the stationary seal after a predefined time

Part hot seal completed

1

2

3


4

5


6

3-6. Manual De-gate + Hot Seal 300° C






Hot seal at 300° C for 3 seconds appears to cover almost 95% of the de-gated area well. The overflows are within the blade thickness.



	January	,		Februa	ary			March			April				May			
	WW29	ww30	WW31	WW32	WW33	WW34	WW35	WW36	WW37	WW38		WW41	WW42	WW43	WW44	WW45	WW46	WW47
2K GBP2 samples to Korat, "type 1" Hot Seal																		
"type 2" Hot Seal development																		
Hot Seal Process DOE (% coverage & LPC)																		
Adhesive coating LCO MSL results																		
Evaluate effectiveness of ultrasonic weld																		
						f .												
HiP: samples for Transport ODT study										7								
Korat: Transport ODT study (vs. controls)								S										
												i						
HiP process bringup for production readiness													7					
Grenada BP2 Production Process Qual build																		
Crawford Gen 3 build																		

•Comments:

- Final hot seal process to be optimized to minimize LPC and maximize % gate seal.
- · Adhesive and ultrasonic options will continue to be explored parallel to primary path.
- Schedule shows GBP2 final process qual after a T-ODT study, but can potentially happen in parallel.
- T-ODT study: cast vs. manual degate vs. hot seal. Need a place to ship ODT passers.
- FEP still refining pad tilts and blade heights. Target dimensionally capable, improved gate parts in Q4.




Grenada/ Bacall BP2 SAD Update



January 14, 2014

GrenadaBP2ºPhase @ate Contract Delta Tracking

	Volume	Phase 0	Phase 0 Update Aug 2013	SAD Update Jan 2014	Delta
-10%	Volume	103M	106M	104M	-1M
-10%	Revenue	5,817.9 M	6,643.2 M	6,642.1 M	-\$1.1M
-2%	Gross Margin %	25%	32%	30%	-2%
+2%	TVC 3 RD QTR	\$29.31	\$28.21	\$25.80	\$24.1
+2%	TVC At SAD	\$32.04	\$29.05	\$26.90	\$-2.15
+10%	Number of SKU's	21	24	24	0




Variance explanation

- •Volume is down due to Ramp adjustment from Q2 to Q3
- •Revenue is down to Ramp adjustment and GM % reduction
- •GM % reduction is due to fully burden cost increase.
 - Factory Utilization decrease raised fully burden cost

Seagate Confidential

Grenada BP1.5 to BP2 Transition



- Source December Revplan
 - Outer Quarters are from Feb LRP
 - 3TB Outer Quarters volumes are 50% of total market (STX Market Research)

Seagate Confidential (#)

Grenada BP2 Financial Summary

1												
Financial Metrics GrenadaBP2 3D												
	Q1CY14	Q2CY14	Q3CY14	Q4CY14	Q1CY15	Q2CY15	Q3CY15	Q4CY15	Q1CY16	Q2CY16	Q3CY16	
	Q3FY14	Q4FY14	Q1FY15	Q2FY15	Q3FY15	Q4FY15	Q1FY16	Q2FY16	Q3FY16	Q4FY16	Q1FY17	
Total Revenue	94.1 M	279.7 M	443.8 M	508.6 M	658.2 M	665.0 M	702.9 M	770.1 M	769.7 M	774.3 M	775.7 M	6,442.1 M
Total TVC	40.4 M	124.4 M	196.8 M	222.5 M	279.1 M	280.7 M	293.8 M	317.1 M	316.4 M	317.7 M	317.7 M	2,706.7 M
Total COGS	64.4 M	197.9 M	317.1 M	361.4 M	462.0 M	465.4 M	489.5 M	532.8 M	531.4 M	533.4 M	533.2 M	4,488.6 M
Total CM	53.8 M	155.3 M	247.0 M	286.0 M	379.1 M	384.3 M	409.0 M	452.9 M	453.3 M	456.6 M	458.1 M	3,735.4 M
CM%	57%	56%	56%	56%	58%	58%	58%	59%	59%	59%	59%	58%
Total GM	29.7 M	81.8 M	126.8 M	147.1 M	196.2 M	199.6 M	213.3 M	237.2 M	238.3 M	240.9 M	242.5 M	1,953.5 M
GM%	32%	29%	29%	29%	30%	30%	30%	31%	31%	31%	31%	30%

- Gross Margin of 30%.
- Average TVC Erosion holds at about 1.3%
- Financials based on 1/2/3TB Native Configs, 500GB and 2TB Weighted Cost based on volume of 1HD 500GB and 3D 4 Hd 2TB Grenada BP2 Volumes needed to consume SSW.

Seagate Confidential (#)

Grenada BP2 SKU Complexity Report

		CUSTOMER UNIQUE RESTRICTIONS																				
GrenadaBP2				Ma	teria	ls			BUILD	TE	CONFIG	LAB	EL	M	MFG Site		CuanadaBB			Complexit	Other Ops	
Customers	HSA Head	Suspension	PreAmp	Media	MBA	Cover	РСВА	Other	Bal Control	GOTF	CustTest	F3	Drive	Case	suz	Wuxi	ТТК	GrenadaBP Vol Units Est (Kaufman)	GrenadaB P2 SKU Count	Mean Vol/SKU (Phase0)	y Cost Model Per Unit	Complexity Cost Per Unit
NLL										NLL	Blue	Spec								#DIV/0!	#DIV/0!	
Apple								Blk Label		OEM1	Blue Nun	Spec						2,773,32	0 6	462,220	\$ 1	
НР												Spec						3,705,89	0 4	926,473	\$ 0	
Lenovo												Spec						4,227,03	3	1,409,013	\$ 0	
Std OEMs																		30,565,84	3	10,188,615	\$ 0	
Disty																		54,548,83	3 4	13,637,209	\$ 0	
Retail																		7,348,71	9 3	2,449,573	\$ 0	
TOTAL																		103,169,649	23	4,485,637		

Seagate Confidential (#)

GrenadaBP2 Volume through FY15

By Segment

	ė.	X.			į.	-	7	4			h.	r.			
Product	Channel	Segment	GB	Vol Q214	Vol Q314	Vol Q414	Vol Q115	Vol Q215	Vol Q315	Vol Q415	Q1 FY16	Q2 FY16	Q3 FY16	Q4 FY16	Q1FY17
			500		26,000	700,000	700,000	700,000	700,000	700,000	700,000	700,000	700,000	700,000	700,000
GrenadaBP2	Disti		1000	0	715,699	1,467,482	1,975,000	2,076,113	2,179,918	2,288,914	2,403,360	2,523,528	2,649,704	2,782,189	2,914,675
			2000	0	425,579	1,129,783	1,350,000	1,576,575	1,655,404	1,738,174	1,825,083	1,916,337	2,012,154	2,112,761	2,213,369
			3000	0	114,560	457,192	600,000	1,025,439	1,076,557	1,016,518	1,160,741	1,514,600	1,409,795	1,312,242	1,214,689
	Disti Total			0	1,281,838	3,754,457	4,625,000	5,378,126	5,611,879	5,743,606	6,089,183	6,654,464	6,771,652	6,907,193	7,042,733
	OEM	DT	1000	0	0	350,000	1,498,638	1,698,638	1,783,569	1,872,748	1,966,385	2,064,704	2,167,940	2,276,337	2,384,734
			2000	0	0	380,000	1,058,500	1,289,925	1,354,421	1,422,142	1,493,249	1,567,912	1,646,307	1,728,623	1,810,938
			3000	0	0	100,000	225,000	838,995	880,819	831,696	949,697	1,239,218	1,153,468	1,073,653	993,837
	OEM Total			0	0	830,000	2,782,138	3,827,558	4,018,810	4,126,586	4,409,332	4,871,834	4,967,716	5,078,612	5,189,509
	SV	SV	1000	0											
			2000	0											
			3000	0											
	SV Total			0	0	0	0	0	0	0	0	0	0	0	0
	Retail	Retail	1000	0	0	100,000	100,000	125,000	125,000	45,000	18,750				
			2000	0	100,000	300,000	300,000	700,000	630,000	585,000	544,600	429,300	337,250	317,800	298,350
			3000	0	63,000	143,852	143,852	246,755	239,949	282,819	263,142	237,000	237,000	213,000	189,000
	Retail Total	Retail Total		0	163,000	543,852	543,852	1,071,755	994,949	912,819	826,492	666,300	574,250	530,800	487,350
Total	Total			0	1,444,838	5,128,309	7,950,989	10,277,440	10,625,637	10,783,011	11,325,007	12,192,598	12,313,618	12,516,605	12,719,591
			1000		710	1 017	2 474	2 775	2.002	4.100	4 270	4 500	4.010	F 0F0	F 200

- Source December 13 Revplan
- Will Consume WTF and SSW 500GB GrenadaBP2 in disti (Volumes Variable)

Seagate Confidential

Complexity Matrix - Grenada BP2

Case 3:16-cv-00523-JCS



Aug 6 2013 Phase 0 Update

Marketing Name		Formatted Capacity	Config	Product Cache	Apple	НР	Lenovo	STD OEM	Disty	Retail	Total	
	D	500	2.0A	64	0	0	0	0	1 (250K-1.5m qtr)	0	1	
	1D	1000	2.0A	64	2	1	1	1	1	1	7	
daBP2	Q	2000	2.0A	64	0	0	0	0	0	1	1	
Grenad	2D	2000	2.5A	64	2	1	1	1	1	0	6	
	3D	0	3000	2.0A	64		0	0	0	0	1	1
		3000	2.5A	64	3	2 (ISS no vol commit)	1.	1	1	0	8	
Grand Total	Grand Total					2	3	3	3	3	24	


Dec 3 2013 Update

Marketing Name		Formatted Capacity	Config	Product Cache	Apple	НР	Lenovo	STD OEM	Disty	Retail	Total
	10	500	2.0A	64	Ö	o	o	o	1 (250K-1.5m qtr)	0	1
	τ	1000	2.0A	64	3	1	i	i	i	1	8
daBP2	2D	2000	2.0A	64	0	0	o	0	0	1	1
Grena	Z	2000	2.5A	64	2	1	1	1	1	0	6
	3D	3000	2.0A	64		0	o	0	0	1	1
	ε	3000	2.5A	64	2	2 (ISS no vol commit)	1	1	1	0	7
Grand Total					7	2	3	3	3	3	24

Move 1 Apple AppleCare requirement = 3.6V Tolerant from 3TB to 1TB

Seagate Confidential (#)

Grenada BP2 VOttstomen Qualification Schedules



Apple: STX communicated in August '13 that BP2 must be qualified by end of June to maintain supply continuity. Apple has still not agreed to this schedule.

Dell: have changed to quarterly block schedule, BP2 falls into CQ3 RTS block.

Lenovo: pulling for early start. Will ship CTUs concurrently with Lenovo EST testing.

HP: Schedule underpinned. March start due to OEM RDT completion in Feb. CTUs ship late Feb.

HIGHLY CONFIDENTIAL


Transition PTC 90

GrenadaBP1.5 to Grenada BP2 transition

	1/15	3/1
		-
BP2	1/15	4/1
BP1.5		
BP2	1/15	3/1
BP1.5		
BP2	1/15	3/1
BP1.5		
BP2	1/15	3/1
BP1.5		
BP2	1/15	3/1
BP1.5		-
BP2	1/15	3/1
BP2	1/15	4/1
BP1.5		
BP2	1/15	3/1
BP		
BP2	1/15	4/1
BP1.5 BP2	10/1	4/1
	BP1.5 BP2	BP2 1/15 BP1.5 BP2 1/15 BP1.5 BP2 1/15 BP1.5 BP2 1/15 BP1.5 BP2 1/16 BP1.5 BP2 1/15 BP1.5 BP2 1/15

OAFWA	ONEW/	DOFWAA	O.F.V.	OFFWE	ODEWAY.	025/45
Q1FY14	Q2FY14	Q3FY14	Q4FY14	Q1FY15	Q2FY15	Q3FY15
JULY '13 AUG '13 SEP '13	OCT '13 NOV '13 DEC '13	JAN '14 FEB '14 MARCH '14	APR '14 MAY '14 JUNE '14	JULY '14 AUG '14 SEP '14	OCT '14 NOV '14 DEC '14	JAN '15 FEB '15 MAR '15
100%	100%	100%	90%	25%	0%	0%
0%	0%	0%	10%	75%	100%	100%
100%	100%	100%	90%	50%	10%	.0%
0%	0%	0%	10%	50%	90%	100%
100%	100%	100%	90%	25%	0%	0%
0%	0%	0%	10%	75%	100%	100%
100%	100%	100%	90%	25%	0%	0%
0%	0%	0%	10%	75%	100%	100%
100%	100%	100%	90%	50%	0%	0%
0%	0%	0%	10%	50%	100%	100%
100%	100%	100%	50%	5%	0%	0%
0%	0%	0%	50%	95%	100%	100%
100%	100%	100%	25%	0%	0%	0%
0%	0%	0%	75%	100%	100%	100%
100%	100%	100%	90%	50%	10%	0%
0%	0%	0%	10%	50%	90%	100%
100%	100%	100%	90%	50%	10%	0%
0%	0%	0%	10%	50%	90%	100%
100%	100%	100%	90%	50%	10%	0%
0%	0%	0%	10%	50%	90%	100%
Q1FY14	Q2FY14	Q3FY14	Q4FY14	Q1FY15	Q2FY15	Q3FY15
100%	100%	94%	74%	28%	2%	0%
0%	0%	6%	26%	72%	98%	100%

GrenadaBP2 Transition




Seagate Confidential (#)

HIGHLY CONFIDENTIAL FED_SEAG0057313

Bacall BP2 Phase Gate Contract Delta Tracking

	Volume	Phase 0	Phase 0 Update Aug 2013	SAD Update Jan 2014	Delta
-10%	Volume	26M	29M	28M	-1M
-10%	Revenue	1,273 M	1,858 M	1,829 M	-29M
-2%	Gross Margin %	24%	36%	35%	-1%
+2%	TVC 3 RD QTR	\$26.77	\$27.38	\$26.60	\$-0.78
+2%	TVC At SAD	\$28.34	\$28.74	\$27.32	\$-1.42
+10%	Number of SKU's	17	21	21	0




Variance Explanation

- •Volume decrease due to Ramp push out to Q4
- •GM% and Revenue decrease due to Ramp push out to Q4 and fully burden cost increase

Seagate Confidential (#)

Bacall BP to BP2 Transition



- Assumptions:
- Video = 55% share, SV = 60% share, NAS = 50% share

Seagate Confidential #

Bacall BP2 Financial Summary

											and the same of th
Financial Metrics Bacali 3D	· · · · · ·										
	Q1CY14	Q2CY14	Q3CY14	Q4CY14	Q1CY15	Q2CY15	Q3CY15	Q4CY15	Q1CY16	Q2CY16	
	Q3FY14	Q4FY14	Q1FY15	Q2FY15	Q3FY15	Q4FY15	Q1FY16	Q2FY16	Q3FY16	Q4FY16	
Total Revenue	1.6 M	94.1 M	212.1 M	233.1 M	236.3 M	235.5 M	231.2 M	208.5 M	193.4 M	183.9 M	1,829.7 M
Total TVC	0.7 M	36.3 M	83.7 M	91.7 M	92.1 M	91.4 M	89.7 M	83.2 M	78.4 M	75.2 M	722.3 M
Total COGS	1.1 M	59.6 M	138.2 M	151.6 M	152.8 M	152.1 M	149.4 M	137.8 M	129.3 M	124.0 M	1,195.9 M
Total CM	0.9 M	57.8 M	128.3 M	141.4 M	144.2 M	144.1 M	141.5 M	125.3 M	115.1 M	108.7 M	1,107.3 M
CM%	57%	61%	61%	61%	61%	61%	61%	60%	59%	59%	61%
Total GM	0.4 M	34.5 M	73.9 M	81.5 M	83.5 M	83.4 M	81.8 M	70.8 M	64.1 M	59.9 M	633.7 M
GM%	28%	37%	35%	35%	35%	35%	35%	34%	33%	33%	35%

- Gross Margin of 35%.
- AUC Erosion starts out at 8% Q3FY14 and works down to 1.2% quarter over quarter by Q3FY15
- Financials based on 1 & 3TB Native Configs, 2TB Weighted Cost based on volume of 1HD 500GB and 3HD 2TB Grenada BP2 Volumes needed to consume SSW.

Seagate Confidential (#)

Bacall BP2 SKU Complexity Report

								CUST	OMER UN	IIQUE F	RESTRIC	TIONS											
BacallBP2				Ma	teria	ıls			BUILD	TI	EST	CONFIG	LAE	EL	M	FG Si	ite				Com	plexity	Other Ops
Customers	Head	ension	PreAmp	Media	MBA	Cover	PCBA	Other	ontrol	GOTF	tTest	F3	Drive	Case	SUZ	Wuxi	¥	BacallBP2 Vol Units Est		Mean Vol/SKU	1	Model	Complevity
	HSA	Suspe	Pre	ž	Σ	သိ	P	ð	Bal C	ő	CustT		ā	ö	S	*	F	(Kaufman)	(Phase0)	(Phase0)	Pe	r Unit	Per Unit
NAS																		4,644,712	2	2,322,356	s	0	
STD OEM 1.5																		730,097	2	365,049	\$	1	
Echostar/ Dish																		1,498,230	3	499,410	\$	1	
Technicolor & Direct TV																		619,310	2	309,655	\$	1	
Echostar/ Bell																		300,000	1	300,000	\$	1	
Surveillance																		3,899,578	3	1,299,859	\$	0	
STD OEM 6G																		1,676,385	3	558,795	\$	0	
STD OEM 3G																		15,087,469	2	7,543,735	\$	0	
Disty																		1,182,864	3	394,288	\$	1	
TOTAL																		29,638,646	21	1,411,364			

Seagate Confidential (#)

Complexity Matrix – Bacall BP2 Phase 0




Marketing Name	Formatted Capacity	Product Cache	Sony	Panasonic	Echostar	Thompson	STD OEM 6G	STD OEM 3G	SV	NAS	Disty	Total
BacallBP2	1000	64	1	1	1	1	1	1	1	0	1	8
Dacallor2	2000	64	1	1	1	1	1	1	1	1	1	9
Grand Total			2	2	2	2	2	2	2	1	2	17

Aug 6 2013

Marketing Name		Formatted Capacity	Product Cache		D OEN 1.5G	1	Fehostar/Sell	Echostar/Dish	Technicolor	STD OEM 6G	STD OEM 3G	sv	NAS	Disty	Total
	1D	1000	64	7	1		1 (30-60K-qtr)	1	1	1	1	1	0	1	8
BacallBP2	2D	2000	64	L	1			1	1	1	1	1	1	7	8
	3D	3000	64		8			1	0	1	0	1 (180K-qtr)	1 (260K-qtr)	1 (17K-qtr)	5
Grand Total					2		0	3	2	3	2	2	1		21

Seagate Confidential



BP2 RDT 400K Demo Timing – Jan 21 (@r soomer)

DVR -


NAS - Gated by Rapid RAID Rebuild functionality and performance test comparisons across segments;

SV - Apr 1 (external);

Baseline
Complete
On Track
Set Base
Qual Cancelled/ Delayed
Not Underpinned

90% CQC Sept '14 BP EOL ~ Dec '14

	•	Task Name ▼	Transition *	CQC ▼	Start -	Finish 🔻	Predecessors *
1		☐ Bacall BP Program Milestones			Wed 1/22/14	Mon 3/31/14	
2	-	CTU (int)			Wed 1/22/14	Wed 1/22/14	
3	-	SAD (int)			Mon 2/10/14	Mon 2/10/14	
4		CTU (est external)			Sat 2/15/14	Sat 2/15/14	
5	===	SAD (est external)			Mon 3/31/14	Mon 3/31/14	
6		☐ Customer Qualifications			Fri 1/31/14	Tue 9/30/14	
7	-	Google Fiber (Humax)	1	3%	Mon 2/17/14	Fri 5/30/14	4
8		Cisco	1	8%	Mon 2/17/14	Fri 8/1/14	4
9	-	APAC Tier 2/3 Channel	1	5%	Mon 2/17/14	Wed 6/4/14	4
10	=	Sony XG System	1		Mon 2/17/14	Tue 7/15/14	4
11		Samsung VD	1	2%	Mon 2/17/14	Fri 5/30/14	4
12		Samsung Techwin	1	1%	Mon 2/17/14	Mon 6/2/14	4
13		Samsung S1	0	4%	Mon 2/17/14	Fri 5/30/14	4
14	1	Echostar	1	41	Mon 2/17/14	Tue 9/2/14	4
15	-	Panasonic	1	3%	Mon 2/17/14	Mon 6/16/14	4
16		Pace	1	8%	Fri 2/28/14	Fri 5/30/14	4
17		BSkyB	1	7	Fri 2/28/14	Tue 9/30/14	4
18	III	Arris (Motorola)	0	2%	Fri 2/28/14	Wed 7/30/14	4
19	-	Humax EMEA	1	1%	Fri 1/31/14	Thu 5/15/14	
20	-	Humax DirecTV	0	4%	Mon 2/17/14	Mon 6/16/14	4
21	-	Taiwan NAS Partners	1	5%	Tue 4/1/14	Tue 7/15/14	4
22	IIII	Taiwan Tier 2	1	4%	Mon 2/17/14	Thu 5/15/14	4



BP2 RDT 400K Demo Timing – Jan 21 (ar sourcer)

DVR – In drive diagnostic readiness being discussed versus the latest Google requirement Grease bump mitigation being included in Jan 15 2TB Humax units. Drive pairing missing

NAS – Gated by Rapid RAID Rebuild functionality and performance test comparisons across segments; Segment studies being initially along to Reput RAID Rebuild feature readmess Jain


10 with testing estimated to complete late Jan.

SV - Apr 1 (external); Internal dates to be solidified by PLM/DE tear

90% CQC Sept '14 BP EOL ~ Dec '14

Baseline Complete On Track M Place Qual Cancelled/ Delayed Not Underpinned

社



BP2 RDT 400K Demo Timing – Jan 21 (or soomer)

DVR – In drive diagnostic readiness being discussed versus the latest Google requirements; Grease bump mitigation being included in Jan 15 2TB Humax units; Drive pairing missing

from base STD OEM offering, so working to understand this intercept

NAS – Gated by Rapid RAID Rebuild functionality and performance test comparisons across segments; Segment builds being included – Jan 6, Rapid RAID Rebuild feature readiness. Jan

SV - Apr 1 (external); Internal dates to be solidified by FLM/DE team

90% CQC Sept '14 BP EOL ~ Dec '14

Baseline Complete On Track va 4 stat Qual Cancelled/ Delayed Not Underpinned

Seagate Confidential

(#)

Grenada BP2 and Bacall BP2 Highlights

- CRT1 Demo'ed 267K, Potential 333Kfor Grenada, 749 DPPM, recommend CTU and SAD Declare
- CRT1 Demo'ed 486K, Potential 710K for Bacall, 437 DPPM, recommend CTU!

GrenadaBP2:

- CRT 1 has achieved CTU metrics. Targeting CTU Declare WW28
 - Investigating a possible Disty SAD from CRT1.
- · OEM FW delivered and is being ECR'ed this week
- 1st CTU shipments are for Apple in WW30
 - AppleCare GBP2 option is being underpinned for early Feb CTUs
- Remaining OEM CTUs aligned to start shipping ~Feb 10th
- Regression Qual on Plastic DSP for Cleanliness and Sealing. CT would like to Seat Plastic DSP in the Feb. CTU's. Not approved for SAD. Plastic DSP would be a CTU Risk.
- Grenada 90% CQC anticipated in June driven by Dell, Lenovo and HP
 - Dell Qual gates 90% CQC and aligns to mid June RTS

BacallBP2:

- Initial OEM FW and feature sets for CTUs delivered this week
- 1st CTUs shipments to Humax & BSkyB in 2nd half of Jan
 Last CTU date is 4/1 for SV
- Bacall 90% CQC anticipated in July-August based on longer qual times
 Customer qual timelines are estimates and not fully underpinned

HIGHLY CONFIDENTIAL FED_SEAG0057322

Grenada BP2-JGR Tum nt 05-5 Stemmary of 1/14/2014

Metric Highlights

DPPM: •Integration

Korat	Wuxi	Suzhou	"ODT"
NA	NA	NA	749

·Goal:

Gen3	SBS	СТИ	SAD	Vol.
10k	8k	4k	2k	500

MTBF:

•Demo:

·Goal:

Validated	Potential	
267K	333K	
Gen 2:	Gen 3:	SAD
50k	100k	250k

TVM:

Pass Rate	Gen3 Goal:
1D: 98%	95%
2D: 99%	95%
3D: 99%	95%

FA / Issue Summary

Open PFLs

Total	< 7	7-15	15-21	21-28	> 28
	Days	Days	Days	Days	Days
19	5	14	0	0	0

Issues

Total	Open	CA Imp.	CA Ver.	Unresolved
0	0	0	0	0

SSO: None

DA: •None

Next Phase Gate/Schedule

Milestone	Date
Gen3 Declare	1/15/2014
CTU Declare	1/15/2014

Issues

- Integration DPPM Completed. 1335 tested 1 failures
 - S/N Z5000DXK EC 7 SOF397304 Media Defect NMD MSD
 - S/N W56000TW EC 7 SOF398892 UDE FW Bug Fix Passed retest
- RDT: CRT 1.0 started on 11/19. 1058 drives running G101DE and x64A servo code. 1197 hrs. 14 failures.
- Particle and Contamination Reduction plan 6 [W56000T0 79] [W56000V9 522] [W56000VZ 7] [Z4X0026C 43] [Z4Z00EZ4 119] [Z4Z00F27 624]
- Data Compare Error 1 [Z4X001YR 188]
- Head Improvements with Stability 2 1 [Z5000E4P 464]
- SWOT fails due to PZT oxidation in BP2 [ISS8796] 1 [Z5000E6P 156]
- Pre comp settings change 1 [Z5000DZ6 249]
- UDE Firmware Bug FIX [ISS8594] 1 [W56000X8 4]
- Unclassified 1 [Z4X0027Y 708]
- Write Aborted Write Uncontrolled 1 [Z4Z00EWV 82]
- ZAP Saturation Fail in CRT1 [ISS8710] 1 [Z4Z00F31 56]
- TVM
- · SZGGD11130A 10 drives Passed
- · KTGGD11049A 10 drives Passed
- KTGGD21082A 10 drives Passed
- KTGGD21050A 30 drives Failed 7 failures xx4C Servo Fixed 6 of them.
- KTGGD41117A 30 drives Passed
- WUGGD41132A 20 drives Failed 1 failure
- · WUGGD41134A 30 drives Passed
- KTGGD61118A 30 drives Passed
- KTGGD61055A 30 drives Failed 1 failure
- WUGGD61135A 30 drives Passed
- Topple
- Z5000E6H EC 7 SOF401030 Plastic DSP

Grenada BP2 CRT 1.0 MTBF/FE

Title: Grenada BP2 CRT 1.0 MTBF/FE Table

AFR(1st year Weibull)
MTBF (1st year Weibull)
2Yr FR (2nd Year Weibull)
3Yr FR (3rd Year Weibull)
4Yr FR (4th Year Weibull)
5Yr FR (5th Year Weibull)

1.039%	Fi
229765	
1.363%	
1.598%	
1.788%	
1.951%	

From all fails Weibull MLE

1058	Qty
14	Failure Qty
2400	POH/Year
0.394	Weibull Beta
1197	Average Test Hours
01/14/14	Date



				Mode	F	E %	Redu	iced AFR	
Issue	Corrective Action	Fix Validation	Qty	AFR %	Demo'd	Potential	Demo'd	Potential	SN/TTF
Particle and Contamination Reduction plans for FOF lines (Prime Phase 10) [ISS8758]	CSI EE auto-self cleaning AUV rabbit clean BUD EE gripper particle reduction(Auto Dycem Cleaning) Gen2 Sleeve for GSS1 Gen2 BLMC Auto Cleaning Clamp Holder Washing Fixture Enclosure Cover plate for GSS Screw driver motor Design a J-Box and add vacuum to block and remove particles for DS2 Bracket with vacuum to remove particles for DS2 2x filtration washing system	-	6	0.43%		15%	0.43%	0.36%	[W56000T0 - 79] [W56000V9 - 522] [W56000VZ - 7] [Z4X0026C - 43] [Z4Z00EZ4 - 119] [Z4Z00F27 - 624]
Data - Compare Error	In Retest		1	0.07%	8		0.07%	0.07%	[Z4X001YR - 188]
Head Improvements with Stability 2 and test	Stability 2 and test enhancements	B	1	0.07%		40%	0.07%	0.04%	[Z5000E4P - 464]
SWOT fails due to PZT oxidation in BP2 [ISS8796]	PZT oxidation leading to SWOTs in BP2. Ongoing monitoring	2	1	0.07%	*	40%	0.07%	0.04%	[Z5000E6P - 156]
Pre comp settings change leading to some of the weak write mitigation [ISS8798]	Higher pre-comp values in RAP	-	1,	0.07%	9	80%	0.07%	0.01%	[Z5000DZ6 - 249]
UDE Firmware Bug FIX [ISS8594]	Reli and SIE verification runs with new F3 code.	5	1	0.07%	100%	100%	0.00%	0.00%	[W56000X8 - 4]
UnClassified Failure	FA in Progress	5	1	0.07%	, v		0.07%	0.07%	[Z4X0027Y - 708]
Write - Aborted Write - Uncontrolled	FA In progress	9	1	0.07%			0.07%	0.07%	[Z4Z00EWV - 82]
ZAP Saturation Fail in CRT1 [ISS8710]	ZAP Saturation check in T275 was disabled by mistake which led to this issue. Fix in PCO 4.3 with CL641737		1	0.07%	100%	100%	0.00%	0.00%	[Z4Z00F31 - 56]

Total Qty. 14

AFR 0.90%

MTBF 267K

0.72% 333K

Grenada BP2 CRT 1.0 168 hr. DPPM

Title: Grenada BP2 CRT 1.0 MTBF/FE Table

168hr DPPM 7561

1058 Qty 8 Failure Qty 01/14/14 Date



Turne	Commention Antique	PiW-1: J:	04	Mode	F	E %	Redu	ced DPPM			
Issue	Corrective Action	Fix Validation (ix validation Qty	rix validation Qty	llidation Qty	DPPM	Demo'd	Potential	Demo'd	Potential	SN/TTF
	CSI EE auto-self cleaning										
	AUV rabbit clean										
	BUD EE gripper particle reduction(Auto										
	Dycem Cleaning)										
	Gen2 Sleeve for GSS1										
	Gen2 BLMC Auto Cleaning	- 4				15%	3781	3213.85			
Particle and Contamination Reduction plans for FOF lines	Clamp Holder Washing Fixture								[W56000T0 - 79] [W56000VZ - 7] [Z4X0026C - 43] [Z4Z00EZ4 - 119]		
(Prime Phase 10) [ISS8758]	Enclosure Cover plate for GSS Screw		4	3781							
D 000 90	driver motor										
	Design a J-Box and add vacuum to block										
	and remove particles for DS2			i							
	Bracket with vacuum to remove particles										
	for DS2										
	2x filtration washing system										
SWOT fails due to PZT oxidation in BP2 [ISS8796]	PZT oxidation leading to SWOTs in BP2.	con	1	945		40%	945	567	[75000500 450]		
SWOT Talls due to FZT Oxidation in BFZ [1338790]	Ongoing monitoring	(5)							[Z5000E6P - 156]		
UDE Firmware Bug FIX [ISS8594]	Reli and SIE verification runs with new F3	108	1	945	100%	100%	0	0	[MECOUONS 4]		
ODE FIRMWARE BUS FIX [1558594]	code.	(5)	1	943	100%	100%	U	0	[W56000X8 - 4]		
Write - Aborted Write - Uncontrolled	FA in Progress	(#	1	945		*	945	945	[Z4Z00EWV - 82]		
	ZAP Saturation check in T275 was										
ZAP Saturation Fail in CRT1 [ISS8710]	disabled by mistake which led to this	(1	945	100%	100%	0	0	[Z4Z00F31 - 56]		
	issue. Fix in PCO 4.3 with CL641737										

Total Qty. 8

DPPM 5671 4725.85

Bacall3:BP22GRTodn015Summary pal/14/2014

Metric Highlights

DPPM: •Integration

Korat	Wuxi	Suzhou	"ODT"
NA	NA	NA	437

•Goal:

Gen3	SBS	СТИ	SAD	Vol.
15k	8k	4k	2k	500

MTBF:

•Demo:

Validate	d	Potential		
486K		710K		
Gen 2:	G	en 3:	сти	SAD
100k	2	00k	400k	550k

TVM:

Pass Rate	Gen3 Goal:
1D: 97%	95%
2D: 100%	95%
3D: 100%	95%

FA / Issue Summary

Open PFLs

Total	< 7	7-15	15-21	21-28	> 28
	Days	Days	Days	Days	Days
20	7	13	0	0	0

Issues

Total	Open	CA Imp.	CA Ver.	Unresolved
0	0	0	0	0

SSO: None

DA: •None

Next Phase Gate/Schedule

Milestone	Date
Gen3 Declare	1/15/2014
CTU Declare	1/15/2014

Issues

- Integration DPPM 1188 Completed. 3 failures
 - · Bad Writes 1
 - · Weak Write 1
 - Head-Degraded Writer 1
- RDT: CRT 1.0 started on 11/21. 985 drives running G101DE and x64A servo code. 1156 hrs. 14 failures
- Particle and Contamination Reduction plans 4 [S5100EY6 42] [S5100F06 234] [W73001BA 195] [W73001F3 303]
- Head Improvements with Stability 2 3 [W72001S8 83] [W73000V6 58] [W7300127 934]
- CCTO outlier fails in BP2 [ISS8795] 2 [W7300125 751] [W730019F 587]
- SWOT fails due to PZT oxidation in BP2 [ISS8796] 2 [W72001EL 4] [W73000W2 514]
- No Error or Symptom Found or Reported 1 [W73000TP 258]
- Write Aborted Write Controlled 1 [S5100F83 7]
- Write BAD Write 1 [W73001MP 7]
- TVM
- SZBGD21045A 30 drives Failed 1 Failure
- WUBGD41046A 30 drives Passed
- WUBGD61083A 15 drives Passed
- · WUBGD61136A 15 drives Passed
- WUBGD61121A 30 drives Passed
- Topple
- S5100ENG EC 7 SOF400173 672KHz Modulation
- · S5100EZ0 EC 7 SOF402206 Head-Degraded Reader

Bacall BP2 CRT 1.0 MTBF/FE

Title: Bacall BP2 CRT 1.0 MTBF/FE Table

AFR(1st year Weibull)
MTBF (1st year Weibull)
2Yr FR (2nd Year Weibull)
3Yr FR (3rd Year Weibull)
4Yr FR (4th Year Weibull)
5Yr FR (5th Year Weibull)

	1.786%	
4	186220	
	2.386%	
	2.825%	
	3.185%	
	3.494%	

From all fails Weibull MLE

985	Qty
14	Failure Qty
8760	POH/Year
0.423	Weibull Beta
1156	Average Test Hours
01/14/14	Date



				Mode	I	E %	Redi	iced AFR				
Issue	Corrective Action	Fix Validation	Qty	AFR %	Demo'd	Potential	Demo'd	Potential	SN/TTF			
Particle and Contamination Reduction plans for FOF lines (Prime Phase 10) [ISS8758]	CSI EE auto-self cleaning AUV rabbit clean BUD EE gripper particle reduction(Auto Dycem Cleaning) Gen2 Sleeve for GSS1 Gen2 BLMC Auto Cleaning Clamp Holder Washing Fixture Enclosure Cover plate for GSS Screw driver motor Design a J-Box and add vacuum to block and remove particles for DS2 Bracket with vacuum to remove particles for DS2 2x filtration washing system	*	4	0.49%	*	15%	0.49%	0.41%	[S5100EY6 - 42] [S5100F06 - 234] [W73001BA - 195] [W73001F3 - 303]			
Head Improvements with Stability 2 and test enhancements [ISS8797]	Stability 2 and test enhancements	ST.	3	0.36%	· €	40%	0.36%	0.22%	[W72001S8 - 83] [W73000V6 - 58] [W7300127 - 934]			
CCTO outlier fails in BP2 [ISS8795]	Have 2 SWD retries before the drive enters RAW mode like BP	ж	2	0.24%		100%	0.24%	0.00%	[W7300125 - 751] [W730019F - 587]			
SWOT fails due to PZT oxidation in BP2 [ISS8796]	PZT oxidation leading to SWOTs in BP2. Ongoing monitoring	×	2	0.24%	1.8:	. 40%		40% 0.24% 0.15%		0.15%	[W72001EL - 4] [W73000W2 - 514]	
No Error or Symptom Found or Reported	In Retest	æ	1	0.12%	16					0.12%	[W73000TP - 258]	
Write - Aborted Write - Controlled	FA in Progress		1	0.12%	ē	ē	0.12%	0.12%	[S5100F83 - 7]			
Write - BAD Write	In Retest		1	0.12%			0.12%	0.12%	[W73001MP - 7]			

Total Qty. 14

AFR 1.79%

1.23%

MTBF 486K

710K

Bacall BP2 CRT 1.0 168 hr. DPPM

Title: Bacall BP2 CRT 1.0 MTBF/FE Table

168hr DPPM 6091

985 Qty
6 Failure Qty
01/14/14 Date



Tague	Compostino Astion	Fin Walidation	Ohr	Mode	F	FE %		ced DPPM	
Issue	Corrective Action	Fix Validation	Qty	DPPM	Demo'd	Potential	Demo'd	Potential	SN/TTF
Head Improvements with Stability 2 and test	Stability 2 and test enhancements	Ħ.	2	2030		40%	2030	1218	[W72001S8 - 83] [W73000V6 - 58]
	CSI EE auto-self cleaning								
	AUV rabbit clean								
	BUD EE gripper particle reduction(Auto								
	Dycem Cleaning)								
	Gen2 Sleeve for GSS1								
	Gen2 BLMC Auto Cleaning								
Particle and Contamination Reduction plans for FOF lines	Clamp Holder Washing Fixture		1	1015		15%	1015	862.75	[S5100EY6 - 42]
(Prime Phase 10) [ISS8758]	Enclosure Cover plate for GSS Screw	-	1	1012	1 80	15%	1012	002./5	[35100E10 - 42]
	driver motor								
	Design a J-Box and add vacuum to block								
	and remove particles for DS2								
	Bracket with vacuum to remove particles								
	for DS2								
	2x filtration washing system								
SWOT fails due to PZT oxidation in BP2 [ISS8796]	PZT oxidation leading to SWOTs in BP2.		4	1015		40%	1015	609	[W72001EL - 4]
39VOT Talls due to F2T Oxidation in BPZ [1338/90]	Ongoing monitoring	-	,1	1012	· ·	40%	1012	009	[W/2001EL - 4]
Write - Aborted Write - Controlled	FA in Progress	월	1	1015	18	Ÿ	1015	1015	[S5100F83 - 7]
Write - BAD Write	In Retest		1	1015	. 8	¥.	1015	1015	[W73001MP - 7]

Total Qty. 6

DPPM 6090

4719.75

Bacall BP2 CRT 1.0 No Plastic DSP

Title: Bacall CRT 1.0 - No Plastic DSP MTBF

AFR(1st year Weibull)
MTBF (1st year Weibull)
2Yr FR (2nd Year Weibull)
3Yr FR (3rd Year Weibull)
4Yr FR (4th Year Weibull)

5Yr FR (5th Year Weibull)

1.485%	Fr
585692	
1.837%	
2.080%	
2.271%	
2.432%	

rom all fails Weibull MLE

653	Qty
8	Failure Qty
8760	POH/Year
0.31	Weibull Beta
1067	Average Test Hours
01/08/14	Date



			Mode		F	E %	Redu	iced AFR	
Issue	Corrective Action	Fix Validation	Qty	AFR %	Demo'd	Potential	Demo'd	Potential	SN/TTF
Head - Degraded Reader	-	-	1	0.17%	r		0.17%	0.17%	[W72001S8 - 83]
Media Defect - NMD Other	•	-	1	0.17%	r		0.17%	0.17%	[W73001BA - 195]
Modulation - ABS Fly Height - Active Read Mod	-	-	1	0.17%		×	0.17%	0.17%	[W73001F3 - 303]
Off-Track SWOT (Single Wedge Off-Track)	-	-	1	0.17%	r	*	0.17%	0.17%	[W72001EL - 4]
Write - Aborted Write - Controlled	•	-	1	0.17%	r	*	0.17%	0.17%	[S5100F83 - 7]
Write - BAD Write		-	1	0.17%	r	*	0.17%	0.17%	[W73001MP - 7]
Write - Skip Write	Je.	-	1	0.17%			0.17%	0.17%	[S5100F06 - 234]
Write - Weak Write Single Sector	-	-	1	0.17%		*	0.17%	0.17%	[S5100EY6 - 42]

Total Qty. 8


AFR 1.48%

1.48%

MTBF 586K

586K

Grenada PP2v-0055-000 Penysie Ced T/122ndge 55 of 128




94% yield. achieved budget.

No gap to BP.

Grenada 500GB Prime yield	MAT1.0	MAT2.0	CRT1.0	WW22	WW23	WW24	WW25	WW26	WW27	WW28	WW29	WW30
Phase/PCO	N/A	GB2_03_1	GB2_04_1	GB2_04_2					GB2_04_3			
Actual (Korat)	N/A	94.4%	93.9%	LV	LV	93.1%	LV	LV	LV			
Volume	N/A	1001	328	LV	LV	4853	LV	LV	LV			
Actual (Wuxi)			94.2%	LV	LV	LV	LV	LV	LV			
Volume			263	LV	LV	LV	LV	LV	LV			
Actual (Suzhou)			NA	LV	LV	LV	LV	LV	LV			
Volume			NA	LV	LV	LV	LV	LV	LV			
Cum Yld (all)			94.1%	LV	LV	LV	LV	LV	LV			
Volume			591	LV	LV	LV	LV	LV	LV			
Budget	87.1%	87.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%

Seagate Confidential #

Grenada CDe 2007-00528-JES Dovarient 155-5 Tribe 021/12/18 Page 56 of 128



93% yield. achieved budget.

0.6% gap to BP


Grenada 1TB Prime yield	MAT1.0	MAT2.0	CRT1.0	WW22	WW23	WW24	WW25	WW26	WW27	WW28	WW29	WW30
Phase/PCO	GB2_02_2	GB2_03_1	GB2_04_1	GB2_04_2					GB2_04_3			
Actual (Korat)	90.9%	91.2%	90.6%	LV	LV	92.3%	89.1%	LV	93.0%			
Volume	778	379	452	LV	LV	5144	992	LV	1286			
Actual (Wuxi)				LV	LV	LV	LV	LV	LV			
Volume				LV	LV	LV	LV	LV	LV			
Actual (Suzhou)				LV	LV	LV	LV	LV	LV			
Volume				LV	LV	LV	LV	LV	LV			
Cum Yld (all)				LV	LV	LV	LV	LV	LV			
Volume				LV	LV	LV	LV	LV	LV			
Budget	89.6%	89.6%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%

Yield Loss	Failure Causes	Status
1.30%	HEAD INSTABILITY_METRIC > 28 or 38	(a) GOTF spec refinements in PCO 5.0 to recover 30 to 40% (b) investigate by TIMO (90x were ship to RHO on W1428) to try with new Stability2.0 test suit,
1.20%	AFH related fails. Primary symptom are from ID roll off due to contam. Higher failure trend on PNG slider vs TK slider	Special builds with 4 legs, between MPT/NHK, TK/PNG slider/ Also add BP to be control to identify where the problem was from.
0.40%	Blister defect from wash process	TCL180 detergent to reduce this. 100% phase in by JAN
0.20%	Apple Bluenun scan failure	Allow downgrade to other OEM or Disty in PCO 5.0

Seagate Confidential (#)

Grenada PP2v-0052-JFB DWijer 18-5 Trie 1912/18 Page 57 of 128





88.8% yield. 1.9% below budget.


3.7% gap to BP

Grenada 2TB/4H Prime yield	MAT1.0	MAT2.0	CRT1.0	WW22	WW23	WW24	WW25	WW26	WW27	WW28	WW29	WW30
Phase/PCO	GB2_02_2	GB2_03_1	GB2_04_1	GB2_04_2					GB2_04_3			
Actual (Korat)	87.6%	87.5%	86.5%	86.5%	89.8%	91.4%	89.8%	LV	88.8%			
Volume	766	405	727	1004	2979	1958	1454	LV	3986			
Actual (Wuxi)												
Volume												
Actual (Suzhou)												
Volume												
Cum Yld (all)												
Volume												
Budget	86.6%	86.6%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%

Yield Loss	Failure Causes	Status
1.80%	HEAD INSTABILITY_METRIC > 28 or 38	(a) GOTF spec refinements in PCO 5.0 to recover 30 to 40% (b) investigate by TIMO (90x were ship to RHO on W1428) to try with new Stability2.0 test suit,
1.50%	AFH related fails. Primary symptom are from ID roll off due to	Special builds with 4 legs, between MPT/NHK, TK/PNG slider/ Also add BP to be control to identify where the problem was from.
0.90%	EC10414 PRE2 : found damage on Spacer issue	Working with SQE to get the closure

Seagate Confidential (#)

Grenada CDe 200-00523-JESB Dovinet 155-5 Tribe 021/2018 Page 58 of 128




88.7% yield. 0.1% below budget.


1.5% gap to BP


Grenada 3TB Prime yield	MAT1.0	MAT2.0	CRT1.0	WW22	WW23	WW24	WW25	WW26	WW27	WW28	WW29	WW30
Phase/PCO	GB2_02_2	GB2_03_1	GB2_04_1	GB2_04_2					GB2_04_3			
Actual (Korat)	80.7%	84.2%	82.8%	88.5%	86.5%	LV	80.7%	LV	88.7%			
WTF ratio (Korat)	0.3%	0.0%	0.0%	0.1%	0.1%	LV	0.5%	LV	0.0%			
Volume	910	236	642	913	1989	LV	1518	LV	1986			
Actual (Wuxi)												
WTF ratio (Wuxi)												
Volume												
Actual (Suzhou)												
WTF ratio (Suzhou)												
Volume												
Cum Yield (all)												
Volume												
Budget	84.4%	84.4%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%


Yield Loss	Failure Causes	Status
2.00%	HEAD INSTABILITY_METRIC > 28 or 38	(a) GOTF spec refinements in PCO 5.0 to recover 30 to 40% (b) investigate by TIMO (90x were ship to RHO on W1428) to try with new Stability2.0 test suit,

Seagate Confidential (#)










Seagate Confidential (#)



Grenada BP2 – CTU & SAD Manufacturing, Product Development & Systems Engineering

January 10, 2014 Kevin Stenvall Tracy French, Walid Seif, Pushpak Jha



HIGHLY CONFIDENTIAL FED_SEAG0057335

Grenada Provide Request

Grenada BP2 Core Team is presenting the following package for your approval for CTU & SAD release of the full family of Grenada BP2 drives, and CTU release of the full family of Bacall BP2 drives. We present this request with only one material restrictions, where Bacall BP2 will use TDK only until RHO + uPemto topple drop CA is in place.

If you have any questions or concerns please contact Pat Dewey, Kevin Stenvall, Andrew Wong, Robert Kolanda, Gary Kelsic, members of the Grenada Core Team.

Go Grenada BP2!



Grenada Cabrillo Support Support 62 of 128

Lombard Clamp, Radial Slope Change, Bacall BP2 topple Drop Issue with RHO

- Bacall BP2 restriction to use only TDK unitl Corrective Action in place.
- Radial Slope Fix incorporated into qualification builds on 1/7 and 1/10. ECD WW32 (risk) WW35 (full)

Grenada BP2 1h - Change to Actuator Arm to support Balance Weight Diameter

Engineering builds and qualification RGA scheduled for February. ECD WW34 (pull in?)

Plastic DSP Cleanliness Improvement

- Optimize the factory wash recipe to include Plastic DSPs. ECD WW34
- Develop/Qualify vendor process to seal DSP gate area for particle mitigation. ECD WW39

Internal Process, Tier 2 No I/O, and 3 Tier

- Support will be in PCO 5.x ECD WW31

BOM Documentation

- GOTF and Depop Waterfall Structure ECD WW29
- 3 Tier Structure in March/April. WW39



Grenada Carrier 1555 Chief Resolution of the Company of the Compan

Product Name: Grenada BP2 & Bacall BP2	Date: 1/9/2014		
Checklist Criteria	Status/Exceptions	Met?	
Inputs			
Changes to Test Process deliverables reviewed and documented	All	✓ YE NC	
Requirements			
	Advanced Process Development / Launch	✓ YE NC	
On going LRP Test Time and Yield Projections	Lead		
Internal Test Process features with Integration Plans	Test Process Achitectur	e ☑ YE ☐ N(←	SED SP, SED/SD&D Reconfig
External Test Process features with Integration Plans	Test Process Achitectur		—HP, Echostar, Panasonic/Son
Include FW Team in Test Process Functional Review (LCO)	AII	✓ YE N(,,
Feature Integration - on going vs identified	Drive Integration	✓ YE N(
Core Team meeting attendance for Test Process and Integration Leads	Drive Integration	✓ YE N(
SBS and CTU Process Readiness (GOTF and Customer Unique) (LCO)	Drive Integration	¥E □N(←	SED & SD&D CCAs
Factory PCO and FA Support	Drive Integration	¥YE □ N(
On going Yields and YIPs	Drive Integration	¥YE □N(
On Going Test Times and TTR Plans	Drive Integration	✓ YE N(
Final Customer Feature Integration Complete	Drive Integration	¥YE □N(
Depop OTF and Reconfig Processes available	Drive Integration	✓ YE N(
Include Customer Tier Performance in Yield Reporting and YIPs	Drive Integration	✓ YE N(
Parametric data analysis reviewed	Drive Integration	✓ YE NC	
Planning / Scheduling			
SPC ID's documented	Test Process Achitectur	e 🗹 YE 🗌 N(
Maturity			
Test Specification Set	Drive Integration	✓ YE NC	
Test Repeatability study completed, including Gage RR	Drive Integration	✓ YE NC	
Test Process ready to achieve CTU / SAD Declare		✓ YE LINC	

Items with arrows have Plan in place for implementation.

HIGHLY CONFIDENTIAL



FED_SEAG0057338





HIGHLY CONFIDENTIAL FED_SEAG0057339

Manufacturing Plan Summary

- FOF process
 - Heavily leveraged from Grenada BP processes, added balance capability to all multi disc configurations.
 - Balance capability added for Grenada BP2 Apple business segment, and Bacall BP2 NSA business segment, but factory can chose to sort on all other customers/business segments for this program.
 - Making changes to CSI, and adding BLVI station to multi disc lines.
 - Leverage Grenada BP Rework Process No Qualification required with exception to recycle Plastice DSPs.
- Manufacturing
 - Korat is the Grenada BP2 Primary Launch, with both Wuxi & SuZhou as secondary sites.
 - Wuxi Bacall BP2 Launch, will be fast follow of Grenada BP2, and Suzhou as secondary site.
 - Training N/A, highly leveraged, can support with factory ramp teams if required
- Test
 - Gemini Based Front & Back-End Test, and 2D and 3D may require use of Headster/ST240
 - Gemini Targeting No I/0 Low Temp Serial Port Process
 - 3 Tier Process will be implemented before PTA



Manufacturing Configurations

- Native Capacity 3D/3TB, 3D/2TB/4H, 2D/2TB/4H, 1D/1TB and 1D/500gB/1H
 - 1H will consist of both Top and Bottom Depop head configurations.
 - 1H, and 3D/4H, configurations will be for SSW Media consumption.
- Waterfall Capacities are 500gB from 1TB, and 2TB from 3TB.

HIGHLY CONFIDENTIAL

- Manufacturing concerned with rework and scrap since there is no 2D waterfall path.
- BD Restriction to have waterfall to Disty and SBS only, due to performance within ±5% constraint.

Product	SN Prefix	SN Prefix	GB	Priority	Waterfall Path	Documented	BD Requested	Remark	Head	Jsage	Media	Usage	Note
Troduct	Apple - Bal	SINTICIA	OD	ritority	waterial rath	STModel#	ProdModel#	Kemark	Native	2nd Sort	DS	SS	Note
Ð	7P	50	3000	1		ST3000DM001	1ER166	Native	6		3		
	7.5	30	2000	1	4	ST2000DM001	1ER164	WTF	6 to 5 or 4		3		Depop/Rezone to Disty/SBS
ren		56	2000	2		ST2000DM001	1ER164	SSW+Native	4		1	2	DBL DP SSW - Grenada BP2
ad	7N	4Z	2000	3		ST2000DM001	1ER164	Native	4		2		
a		4Y	1000	1		ST1000DM003	1ER162	Native	2		1		
ВР		41	500	1	1	ST500DM002	1ER14C	WTF	1		1		Depop/Rezone to Disty/SBS
P 2		4X	500	1		ST500DM002	1ER14C	Native	1		1	1	TOP Depop SSW
10		53	500	1		ST500DM002	1ER14C	Native	1		1	1	BTM Depop SSW
Product	SN Prefix	SN Prefix	GB	Driority	Waterfall Path	Documented	BD Requested	Remark	Head	Jsage	Media	Usage	Note
Product	NAS - Bal	SIN PIEIIX	GB	Priority	wateriali Patri	STModel#	ProdModel#	Remark	Native	2nd Sort	DS	SS	Note
	73	6A	3000	1		ST1000VM001	1ET166	Native	6		3		
DII DD2	/3	0A	2000	1	+	ST1000VM003	1ET164	WTF	6 to 5 or 4		3		Depop/Rezone to Disty
Bacall BP2	72	51	2000	2		ST1000VM003	1ET164	Native	4		2		
	NA	52	1000	1		ST1000VM002	1ET162	Native	2		1		



Grenada Bacalt BP2/L'RP 52-05

Grenada: -	1			Prime	yield			Insertio	n yield		Total Te	e <mark>st Tim</mark> e(w MQM	adder)	17	Gemin P	ackcap		Insertion throughput yiel			yield
Product	HD	CAP	Q414	Q115	Q215	Q315	Q414	Q115	Q215	Q315	Q414	Q115	Q215	Q315	Q414	Q115	Q215	Q315	Q414	Q115	Q215	Q315
GrenadaBP	2	1000	93.5%	93.5%	93.5%	93.5%	93.0%	93.0%	93.0%	93.0%	39.1	39.1	39.1	39.1	1,256	1,256	1,256	1,256	97.5%	97.5%	97.5%	97.5%
GrenadaBP	4	2000	91.5%	91.5%	91.5%	91.5%	90.0%	90.0%	90.0%	90.0%	72.9	72.9	72.9	72.9	655	655	655	655	91.6%	91.6%	91.6%	91.6%
GrenadaBP	6	3000	90.0%	90.0%	90.0%	90.0%	89.0%	89.0%	89.0%	89.0%	105.0	105.0	105.0	105.0	450	450	450	450	97.0%	97.0%	97.0%	97.0%
GrenadaBP2	2	1000	93.6%	93.6%	93.6%	93.6%	93.0%	93.0%	93.0%	93.0%	37.4	37.4	37.4	37.4	1,315	1,315	1,315	1,314	97.5%	97.5%	97.5%	97.5%
GrenadaBP2	4	2000	92.2%	92.2%	92.2%	92.2%	90.5%	90.5%	90.5%	90.5%	69.1	69.1	69.1	69.1	695	695	695	695	91.6%	91.6%	91.6%	91.6%
GrenadaBP2	6	3000	90.5%	90.5%	90.5%	90.5%	89.3%	89.3%	89.3%	89.3%	103.9	103.9	103.9	103.9	457	457	457	457	97.0%	97.0%	97.0%	97.0%
Delta																						
BP2 vs BP	2	1000	0.1%	0.1%	0.1%	0.1%	0.0%	0.0%	0.0%	0.0%	-1.7	-1.7	-1.7	-1.7	59	59	59	58	0.0%	0.0%	0.0%	0.0%
BP2 vs BP	4	2000	0.7%	0.7%	0.7%	0.7%	0.5%	0.5%	0.5%	0.5%	-3.8	-3.8	-3.8	-3.8	40	40	40	40	0.0%	0.0%	0.0%	0.0%
BP2 vs BP	6	3000	0.5%	0.5%	0.5%	0.5%	0.3%	0.3%	0.3%	0.3%	-1.1	-1.1	-1.1	-1.1	6	6	6	6	0.0%	0.0%	0.0%	0.0%
1																						
Bacall: -				Prime	yield			Insertio	n yield		Total Te	est Time(w MQM	adder)	19	Gemin P	ackcap		Insert	ion thro	ughput	yield
Bacall: - Product	HD	CAP	Q414	Prime Q115	yield Q215	Q315	Q414	Insertio Q115	on yield Q215	Q315	Total Te	est Time(Q115	(w MQM Q215	Q315	Q414	Gemin P Q115	Q215	Q315	Insert Q414	tion thro Q115	Q215	yield Q315
	HD 2	CAP 1000		Q115	Q215	Q315 93.5%	Q414	Q115	Q215	Q315 92.5%			* 7						Q414	Q115	Q215	•
Product	-		93.5%	Q115 93.5%	Q215	93.5%	Q414 92.5%	Q115 92.5%	Q215	92.5%	Q414	Q115	Q215	Q315	Q414	Q115	Q215	Q315	Q414 93.5%	Q115 93.5%	Q215	Q315 93.5%
Product BacallBP	-	1000	93.5%	Q115 93.5%	Q215 93.5%	93.5%	Q414 92.5%	Q115 92.5%	Q215 92.5%	92.5%	Q414 46.9	Q115 46.9	Q215 46.9	Q315 46.9	Q414 1,039	Q115 1,039	Q215 1,039	Q315 1,039	Q414 93.5%	Q115 93.5%	Q215 93.5%	Q315 93.5%
Product BacallBP	-	1000	93.5%	Q115 93.5% 91.0%	Q215 93.5% 91.0%	93.5%	Q414 92.5% 89.5%	Q115 92.5% 89.5%	Q215 92.5% 89.5%	92.5%	Q414 46.9	Q115 46.9	Q215 46.9	Q315 46.9	Q414 1,039	Q115 1,039	Q215 1,039	Q315 1,039	Q414 93.5%	Q115 93.5% 92.5%	Q215 93.5% 92.5%	Q315 93.5%
Product BacalIBP BacalIBP	2 4	1000 2000	93.5% 91.0% 93.0%	Q115 93.5% 91.0% 93.2%	Q215 93.5% 91.0% 93.2%	93.5% 91.0% 93.2%	Q414 92.5% 89.5%	Q115 92.5% 89.5% 92.5%	92.5% 89.5% 92.5%	92.5% 89.5%	Q414 46.9 83.5	Q115 46.9 83.5	Q215 46.9 83.5 45.3 82.5	Q315 46.9 83.5	Q414 1,039 570	Q115 1,039 570 1,077 570	Q215 1,039 570	Q315 1,039 570	Q414 93.5% 92.5%	Q115 93.5% 92.5% 93.5%	93.5% 92.5% 93.5%	Q315 93.5% 92.5%
Product BacalIBP BacalIBP BacalIBP2	2 4	1000 2000	93.5% 91.0% 93.0% 91.5%	Q115 93.5% 91.0% 93.2%	Q215 93.5% 91.0% 93.2% 91.7%	93.5% 91.0% 93.2%	Q414 92.5% 89.5% 92.5% 89.5%	Q115 92.5% 89.5% 92.5% 89.5%	Q215 92.5% 89.5% 92.5% 89.5%	92.5% 89.5% 92.5%	Q414 46.9 83.5	Q115 46.9 83.5 45.3	Q215 46.9 83.5	Q315 46.9 83.5	Q414 1,039 570	Q115 1,039 570	Q215 1,039 570	Q315 1,039 570	Q414 93.5% 92.5% 93.5% 92.5%	Q115 93.5% 92.5% 93.5% 92.5%	Q215 93.5% 92.5% 93.5% 92.5%	Q315 93.5% 92.5% 93.5%
Product BacalIBP BacalIBP2 BacalIBP2 BacalIBP2 BacalIBP2 Delta	2 4	1000 2000 1000 2000	93.5% 91.0% 93.0% 91.5% 90.1%	Q115 93.5% 91.0% 93.2% 91.7%	Q215 93.5% 91.0% 93.2% 91.7%	93.5% 91.0% 93.2% 91.7% 90.1%	Q414 92.5% 89.5% 92.5% 89.5%	Q115 92.5% 89.5% 92.5% 89.5%	Q215 92.5% 89.5% 92.5% 89.5%	92.5% 89.5% 92.5% 89.5%	Q414 46.9 83.5 47.3 84.5	Q115 46.9 83.5 45.3 83.5	Q215 46.9 83.5 45.3 82.5	Q315 46.9 83.5 45.3 82.5	Q414 1,039 570 1,031 563	Q115 1,039 570 1,077 570	Q215 1,039 570 1,077 576	Q315 1,039 570 1,077 576	Q414 93.5% 92.5% 93.5% 92.5%	Q115 93.5% 92.5% 93.5% 92.5%	Q215 93.5% 92.5% 93.5% 92.5%	Q315 93.5% 92.5% 93.5% 92.5%
Product BacalIBP BacalIBP2 BacalIBP2 BacalIBP2 BacalIBP2	2 4	1000 2000 1000 2000	93.5% 91.0% 93.0% 91.5%	Q115 93.5% 91.0% 93.2% 91.7%	Q215 93.5% 91.0% 93.2% 91.7%	93.5% 91.0% 93.2% 91.7%	Q414 92.5% 89.5% 92.5% 89.5%	Q115 92.5% 89.5% 92.5% 89.5%	Q215 92.5% 89.5% 92.5% 89.5%	92.5% 89.5% 92.5% 89.5%	Q414 46.9 83.5 47.3 84.5	Q115 46.9 83.5 45.3 83.5	Q215 46.9 83.5 45.3 82.5	Q315 46.9 83.5 45.3 82.5	Q414 1,039 570 1,031 563	Q115 1,039 570 1,077 570	Q215 1,039 570 1,077 576	Q315 1,039 570 1,077 576	Q414 93.5% 92.5% 93.5% 92.5%	Q115 93.5% 92.5% 93.5% 92.5%	Q215 93.5% 92.5% 93.5% 92.5%	Q315 93.5% 92.5% 93.5% 92.5%
Product BacalIBP BacalIBP2 BacalIBP2 BacalIBP2 BacalIBP2 Delta	2 4 6	1000 2000 1000 2000 3000	93.5% 91.0% 93.0% 91.5% 90.1%	Q115 93.5% 91.0% 93.2% 91.7% 90.1%	Q215 93.5% 91.0% 93.2% 91.7% 90.1%	93.5% 91.0% 93.2% 91.7% 90.1%	Q414 92.5% 89.5% 92.5% 89.5% 85.7%	Q115 92.5% 89.5% 92.5% 89.5% 86.1%	Q215 92.5% 89.5% 92.5% 89.5% 86.1%	92.5% 89.5% 92.5% 89.5% 86.1%	Q414 46.9 83.5 47.3 84.5 121.7	Q115 46.9 83.5 45.3 83.5 120.7	Q215 46.9 83.5 45.3 82.5 119.7	Q315 46.9 83.5 45.3 82.5 119.7	Q414 1,039 570 1,031 563 377	Q115 1,039 570 1,077 570 381	Q215 1,039 570 1,077 576 384	Q315 1,039 570 1,077 576 384	Q414 93.5% 92.5% 93.5% 92.5% 93.0%	Q115 93.5% 92.5% 93.5% 92.5% 93.0%	Q215 93.5% 92.5% 93.5% 92.5% 93.0%	Q315 93.5% 92.5% 93.5% 92.5% 93.0%
Product BacalIBP BacalIBP2 BacalIBP2 BacalIBP2 BacalIBP2 Delta BP2 vs BP	2 4 6 2	1000 2000 1000 2000 3000	93.5% 91.0% 93.0% 91.5% 90.1%	Q115 93.5% 91.0% 93.2% 91.7% 90.1%	Q215 93.5% 91.0% 93.2% 91.7% 90.1%	93.5% 91.0% 93.2% 91.7% 90.1%	Q414 92.5% 89.5% 92.5% 89.5% 85.7%	Q115 92.5% 89.5% 92.5% 89.5% 86.1%	Q215 92.5% 89.5% 92.5% 89.5% 86.1%	92.5% 89.5% 92.5% 89.5% 86.1%	Q414 46.9 83.5 47.3 84.5 121.7	Q115 46.9 83.5 45.3 83.5 120.7	Q215 46.9 83.5 45.3 82.5 119.7	Q315 46.9 83.5 45.3 82.5 119.7	Q414 1,039 570 1,031 563 377	Q115 1,039 570 1,077 570 381	Q215 1,039 570 1,077 576 384	Q315 1,039 570 1,077 576 384	Q414 93.5% 92.5% 93.5% 92.5% 93.0%	Q115 93.5% 92.5% 93.5% 92.5% 93.0%	Q215 93.5% 92.5% 93.5% 92.5% 93.0%	Q315 93.5% 92.5% 93.5% 92.5% 93.0%

Note: BacallBP 2TB insertion yield Q414 projection 89.5% vs 90%(Q214 actual)

						_							
			Bacall/0	Grenada	i	В	acall/Gr	enadaB	P2		Delta (E	3P2 - BP)
	ET Yield	Q414	Q115	Q215	Q315	Q414	Q115	Q215	Q315	Q414	Q115	Q215	Q315
	Low Sort	3.5%	3.5%	3.5%	3.5%	0.0%	0.0%	0.0%	0.0%	-3.5%	-3.5%	-3.5%	-3.5%
	Native	86.3%	87.5%	87.8%	88.5%	91.1%	91.5%	91.9%	92.5%	4.8%	4.0%	4.0%	4.0%
	Cum				92.0%						0.5%	0.5%	0.5%
	Slider Yield	83.0%	83.0%	83.2%	84.0%	82.0%	82.2%	83.0%	83.0%	-1.070	-0.070	-U.Z /0	-1.070
7													

LRP 52 - 06 BBP2, Yield +.5% & Test Time -.5hr

Seagate ((C)

Case 3:16-cv-00523-JCS Document 155-5 Filed 01/12/18 Page 68 of 128 Grenada/Bacall BP2, LCO52-05 Yields

Summary:

- Grenada BP2 Updated to match expected YIP yield gains.
- Bacall BP2 Updated to match expected YIP yield gains.

					Composite F	Prime Yield				
Design					(SAD +1_	Prime Yield (SAD +4	Prime Yield (SAD +7	Prime Yield (SAD +10	Prime Yield (SAD +13	
Cen	SAD 🐣	Detailed Product Name	Hea 🐣	Capac	Mo) 🔻	Mos) *	Mos)	Mos) *	Mos) X	Mos)
LCO	22-Jan-2014	BacallBP2	6	3000	88.8%	90.1%	90.1%	90.1%	90.1%	90.1%
LCO	22-Jan-2014	BacalIBP2	4	2000	90.7%	91.5%	91.7%	91.7%	91.7%	91.7%
LCO	22-Jan-2014	BacallBP2	2	1000	92.7%	93.0%	93.2%	93.2%	93.2%	93.2%
LCO	22-Jan-2014	GrenadaBP2	6	3000	89.5%	90.5%	90.5%	90.5%	90.5%	90.5%
LCO	22-Jan-2014	GrenadaBP2	4	2000	91.2%	92.2%	92.2%	92.2%	92.2%	92.2%
LCO	22-Jan-2014	GrenadaBP2	2	1000	93.1%	93.6%	93.6%	93.6%	93.6%	93.6%
LCO	22-Jan-2014	GrenadaBP2	1	500	90.2%	91.2%	91.2%	91.2%	91.2%	91.2%
LCO	22-Jan-2014	BacallBP2-Throughput	6	3000	95.0%	97.0%	97.0%	97.0%	97.0%	97.0%
LCO	22-Jan-2014	GrenadaBP2-Throughput	6	3000	97.3%	97.7%	98.0%	98.0%	98.0%	98.0%
LCO	22-Jan-2014	GrenadaBP2-Throughput	4	2000	92.7%	93.5%	93.7%	93.7%	93.7%	93.7%
LCO	22-Jan-2014	GrenadaBP2-Throughput	2	1000	95.1%	97.0%	98.0%	98.0%	98.0%	98.0%
LCO	22-Jan-2014	GrenadaBP2-Throughput	1	500	91.1%	92.1%	92.2%	92.2%	92.2%	92.2%

<u>LRP 52 - 06</u> BBP2, Yields increased .5% on 1TB



Case 3:16-cv-00523-JCS Document 155-5 Filed 01/12/18 Page 69 of 128 Grenada/Bacall BP2, LCO 52-05 Test Times

Summary:

- Grenada BP2, changed SP & I/O times to reflect "No I/O" @ 40% of volume.
- Bacall BP2, reduced times to reflect current PCO test time improvements.

					Composite Test Time								
Design.					Test Time (SAD +1	Test Time (SAD +4			E. S. C. S. C. S. C.	Test Time (SAD +16			
Cen *	SAD 💌	Detailed Product Na ✓	Hea 🔨	Capac	Mo) *	Mos	Mos	Mos	Mos	Mos			
LCO	22-Jan-2014	BacallBP2	6	3000	115.7	115.7	115.7	115.7	115.7	115.7			
LCO	22-Jan-2014	BacallBP2	4	2000	79.5	79.5	79.5	79.5	79.5	79.5			
LCO	22-Jan-2014	BacallBP2	2	1000	43.3	43.3	43.3	43.3	43.3	43.3			
LCO	22-Jan-2014	GrenadaBP2	6	3000	100.2	100.2	100.2	100.2	100.2	100.2			
LCO	22-Jan-2014	GrenadaBP2	4	2000	67.8	67.8	67.8	67.8	67.8	67.8			
LCO	22-Jan-2014	GrenadaBP2	2	1000	37.1	36.9	36.7	36.5	36.3	36.3			
LCO	22-Jan-2014	GrenadaBP2	1	500	22.1	22.0	21.9	21.8	21.7	21.7			

LRP 52 - 06

BBP2, Test Times decreased .5 hours on 1TB & 2TB..





Projected Configuration Plan

Marketing Name		Formatted Capacity	Config	Product Cache	Apple	НР	Lenovo	Samsung	Fujitsu	Dell	STD OEM	Disty	Retail	Total
Tab					040	020	540	N/A	500	500	500	300	570	
	1D	1000	2.0A	64	2	1	1	0	0	0	1	1	1	7
BP 2	2D	2000	2.0A	64	0	0	0	0	0	0	0	0	1	1
nadal	7	2000	2.5A	64	2	1	1	0	0	0	1	1	0	6
Gre	3D	3000	2.0A	64		0	0	0	0	0	0	0	1	1
	8	3000	2.5A	64	2	1	1	0	0	0	1,	1	0	6
Grand Total					6	3	3	0	0	0	3	3	3	21

Grenada BP had 25 Configs not including NLL,SMR, SV, and St

Grenada BP to BP1.5 to BP2

HIGHLY CONFIDENTIAL

3/12/13

FED_SEAG0057345

CC Transition Matrix													
Customer Current BP CC 1CH16x- Migrate to BP1.5 CUrrent BP CTU Tab Expected BP2 CTU Tab 1ER16x- Expected BP2 CTU Tab 1ER16x- 1EXPECTU Tab 1ER16x- Expected BP2 CTU Tab 1ER16x- 1EXPECTU Tab 1ER16x- 1EXPECTU Tab 1EXP													
SBS / Retail (2.0A)	572	575 *	904	911 *	910	570							
Disty (2.5A)	302	305	903	910	900	300							
Dell / Std OEM(2.5A)	501	510	903	910	900	500							
Std OEM (2.0A)	505	515 *	904	911 *	910	510							
HP	020	020	021	021	020	020							
Lenovo	543	544	543	544	540	540							
Samsung 2TB	230	231	903	910	NA	NA							
Apple	042	NA	701	NA	700	040							

GrenadaBP2 Restrictions & Plan

Grenada	Volume	J	MATERIAL								BUILD			CONFIG	LABEL		MFG Site				
Customers	%			PCBA		H SA Head	Suspension	PreAmp	Media	МВА	MBA Cover	Other	Bal Control	GOTF	CustTest	F3	Drive	Case	SUZ	Wuxi	TTk
Odotomoro	,,,		Chip	Туре	T an tiess	Suspension	Tierany				- Cuici	- Cur control		Custical		2				1300	
		1										TO THE TAXABLE									
Apple	3%	Н									Black LABEL	10:FBP2<12.6 20:FBP2<15.7	OEM1A	Apple BlueNum	AP15	2	11				
. фр.о											Non SET05 W/F	3D: FPB2<15.7	The state of the s	Full pack 0s							
		11										1D:FBP2<17.6				700					
HP	5%	Н										2D:FBP2<28		Dell PPID	HP32	1	1				
		1										3D: FPB2<30.8 1D:FBP2<17.6	-				-				
Lenovo	4%	Н										2D:FBP2<28		Dell PPID	CC56	1	1				
		П										3D: FPB2<30.8									
STD	30%	Ш										1D:FBP2<17.6		0.11.0010							
OEMs	30%	Н										2D:FBP2<28 3D: FPB2<30.8		Dell PPID							
Disty	60%	Ш										1D:FBP2<17.6		Dell PPID							
Disty	00%	Н										2D:FBP2<28 3D: FPB2<30.8		Dell PPID							
Retail	3%											1D:FBP2<17.6		Dell PPID							
	376											2D:FBP2<28 3D: FPB2<30.8		Dell'PPID							



Improvements from GrenadaBP

- Remove all Suspension and Media restrictions from BP
- Remove all GOTF restrictions except for Apple



Complexity Matrix – Bacall BP2

Bacall BP2	Volume	ne MATERIAL								BUILD Test			CONFIG	LABEL		MFG Site				
Blockpoint	%	PCB	Туре	H SA Head	H SA Sort	Suspension	PreAmp	Media	МВА	Cover	Other	Bal Control	GOTF CustTest		F3	Drive	Case	SUZ	Wuxi	TTk
Sony	1.0%											FBP2<12.4 1D FBP2<20.1 2D		Full pack 0s, Sony MQM, 1.5G lockdown	NYC1		Unique			
Panasonic	1.0%											FBP2<12.4		1.5G lockdown,AV Scan	MAC1		Unique			
EchoStar	27.0%											FBP2<12.4 1D FBP2<20.1 2D		Full pack 0s , POIS, 3D ES Security,LONG DST	ESC1					
THOMSON	1.0%											FBP2<12.4		3G lockdown, POIS test						
STD OEM	51.0%											FBP2<12.4 1D FBP2<20.1 2D								
Std Disty	7.0%																			

No Restriction

Customer Restriction

Seagate Restriction

Restriction with action

Marketing Name	Formatted Capacity	Product Cache	Sony	Panasonic	Echostar	Thompson	STD OEM 6G	STD OEM 3G	sv	NAS	Disty	Total
BacallBP2	1000	64	1	1	1	1	1	1	1	0	1	8
	2000	64	1	1	1	1	1	1	1	1	1	9
Grand Total			2	2	2	2	2	2	2	1	2	17

- Bacall BP CE to BP2 CE is (16 Configs BP to 14 Configs BP2)
- Addition of SV and NAS totals 17 for BP2



20-3:16-cv-00523-JCS Document 15 Deliver to CT ed 01/12/18 Page 73 of 128 Grenada BP2 / Bacall BP2 PCO 5.0 (Next code lockdowr 1/16/2014 PCO) Factory release 1/30/2014 Yield New General CM load Request Factory Purpose: TBD DPPM **Improve** TTR MTBF CL Feature Goodness Redcution date checkin ment New SIC code REL.SATA.643970: X 643870 X Add Bacall B2 tab 911 to CE1 BS 1/8/2014 650589 X Add tab 702 to CTUA for iMac-AppleCare CTU 1/9/2014 Revert CL631789 to remove T240 GAIN DELTA LIM parameter, effectively set it to default of 200 instead of X 1/7/2014 X Enable downgrade for blue nun failure 1/7/2014 Make 'signed' SF3 X 1/7/2014 Fix FAIL PROC issue. Move Fail Proc code block to Display V4 (Alt list), and critical event log information X towards the end of the method 1/7/2014 650920 T315 DISTI only fail criteria request that I had previously sent to be modified as follows: If (315 instability metric >38), then fail only if any one of the following five conditions is also true: condition 1: max(T250RAW ERROR RATE)@BER1 > -2.2 condition 2: stdev(T250RAW_ERROR_RATE)@BER1/mean(T250 RAW_ERROR_RATE)@BER1 > 0.1 X condition 3: abs/mean(T250RAW_ERROR_RATE)@BER1 - mean(T250 RAW_ERROR_RATE)@READ condition 4: (p297 hd instby BIE SUM FULL SIGMA)@FNC2>900 condition 5: (p297 hd instby BIE SUM FULL SIGMA)@CAL2>900 12/10/2013 3-tier system [Andre] by mid January X 12/20/2013 Combine SD&D and SED PF3 tragets into one X 12/20/2013 Fix SED to SDnD reConfig X 12/12/2013 SPT ONLY - tier 2 support X 10/14/2013 X Add CUST CFG to SPT ONLY process, needed to support Tier 2 10/18/2013 Depop OTF FNC2 11049 [Dave K] X X X 7/9/2013 CM Load improvement from Makara X 10/21/2013 X Support STS process 11/7/2013 T50 failure with no retry in different zone T285 (Locate Ramp) algorithm improvement [Bill Ray] Fix 10427 EC X X 11/20/2013 Sync up to BP PCO 9.7E3 11/25/2013 Reset SATA speed on reconfig (implement the serial port method instead of the interface command) Requires F3 support, Ensure HP works. PDD-0217062: BIST reset [[Luxor.*]] X 3/7/2013 552901 Validate all remaining tabs (HP, E*) X 10/14/2013 Channel Opti - restrict Precomp values in RAP for bad/weak write improvements [Vance] 10/24/2013 Conditional Testing for CCT on drives with signs of head instabilities. [Jon] X GOTF screen for SMART log fails 12/18/2013 Propose a spec of >4500 verified errors for any head/zone in P109 SUM HD ZN. Pending data analysis X 12/16/2013 set a new GOTF spec for the Rhtr in AFH3, Test Type=Burnish on the Burnish Check parameter to +14A [Abhi X B. / Terry H.] Pending data analysis 1/6/2014

Grenada BP2 / Bacall BR2 BCO 4.3 (Loasten	Deliver to (OW D. I	od 01/	11/1	19/2013	74	of 120			
	€600€ 166kg	ow n	2/1/ 12/1	9/2013 a	t risk for (I <u>GE 74 (</u> 3BP2	DI 128			
PCO)	Factory rel	ease	12/23/2		ase for Ba enada	icall and				
Purpose: Masspro yield improvements	Yield Improvemen t	TTR	MTBF	DPPM	New	General Goodness	CM load Redcution	Request date	Factory checkin	CL
Validate Echostar					X			10/14/2013		644694
Add SBS tab -569					X			10/17/0010		644615 T 644626 B
								12/17/2013		635875 T
										638975 T
Fix T135 EC42187 FNC2, improve retries [Dick Martin]	X							10/21/2013		639304 T 639395 B
CL619033 "PFR-0234950: Add feature LODT control by send attribute										614153 T
Enable switch FE_0234653_497324_P_CONTROL_ATTR_LODT_FEATURE								11/20/2013	X	636004 B
Re-PRE2 'SETUP_PROC' after recovery PWL for protect drive depop mapping worng Physical HeadRe- PRE2 'SETUP_PROC' after recovery PWL for protect drive depop mapping worng Physical Head					X			11/19/2013	×	635250 T 636010 B
Enable P399 ASYM SUMMARY in EDW					X	Х		11/27/2013		637642
										644038 T 644049 B
Display V4 (Alt list) information in 'FAIL PROC SPT' state for ADG support	X							12/12/2013		643522 B
Change USAE OTFRegressionOrder from 0x0401 to 0x0402 to make SAE Consigned heads use a 2nd orde fit instead of 1st order fit after 4 points are collected.	r				X			12/17/2013		644639 T 644665 B
It instead of 1st order it after 4 points are conected,					^			12/11/2013		644633
								10/17/0010		644684
T297 changes for TTR and more effective identification of bi-modal heads, integrate CL644343		X						12/17/2013		644686 643482 T
FNC2 T297 - (a) Add parameter PERCENT_LIMIT_and set it to 0. (b) Set bit 1 of CWORD1			X					12/13/2013		643499 B
Add retry T185 When drive fail EC14670 , then retest T185 again with optimize setting T185 on GrenadaBP as detail below. 'LO_RAMP_CONT_MAXCYL' from (0,250) to (0,12789) 'START_CYL' from (0,11800) to (0.13800) 'TK0_LIMIT' from 22980 to 25280	×							12/12/2013		620025 BP B 643236 B 644595 B
Temporarily moving from T285 to T185.	X							12/9/2013		642749
Integrate CL641737 PFR-0244109: ZAP. T175/T275. Enable ZAP saturation check.			X	Х		Х		12/11/2013		641737 T 642356 B 640804 T
T221 - DAC TO HEAT PWR FACTOR = 67 for TI and 71 for LSI	x							12/5/2013		640806 B
Move RUN T297 state to before RUN T315 SUM state in FNC2						Х		12/6/2013		640682 T 640758 B
Add T335 retry to recover EC42188 for POST_AFH run	X							12/4/2013		639543 T 639545 B
								TE WEST		562041
SED code support. Fix 100% FIN2 14616-FDE Start Session Failed: T577 FDE Personalization Error. Only IO so far.					X			7/10/2013		639410 639428
								7710/2010		639349 T
Add PF3 retry to T62 to recover EC10560 (from BP)	X							12/3/2013		639411 B 622670 T
Merge CL622670 - Updated T248 to add GetMargin retries, moving to nearby tracks. Fix EC10522 at FIN2	X							11/29/2013		638896 B
Remove GOTF Spec P2109 DFS BER STATS->HARD BER >= 4.3 and SSER < 2.8 Bit 18	X							11/22/2013		637717 T 637722 B
Pick and choose servo for SD&D only (F3/PF3)										
ALL.LOD file combining F3 and servo code [Pushpak]				-	X			5/17/2013		637210
T320 - make it fail safe for OTC data collection in FNC2 [Jon]	X							11/26/2013		637216
Enable new GOTF spec to fail drives in T-25 for LOAD_PEAK_CUR STDEV > 10 EC 10279			Х	Х				11/20/2013		635401 635402
Remove GOTF on P275 ZAP AUDIT STATS2 for MAX 3SIGNRO for Apple						X		11/20/2013		634884 634886
								11/20/2013		634514
Fix typo in GOTF for table P275_ZAP_AUDIT_STATS2_for Apple			Х			Χ		11/19/2013		634521
LUCULY CONFIDENTIAL									F 4 C C C C	

HIGHLY CONFIDENTIAL

			Criteria_Val Num	Vio	Grade_P		
Criteria_Table	Criteria_Column	Criteria_Op	ue latio			il_Code Filter1_Item	Filter1_Op
P2109_DFS_ERROR_STATS_BY_HEAD	TOTAL_UNVFYD_ERR_CNT_BY_HEAD	LESS THAN	370000	OCE1,CTUA/B,OEM1A/B/F,STD	0		
						AVG_RAW_ERR_RATE_FIN	2
P250_AVERAGE_BER_DELTA_BY_HEAD	AVG_RAW_ERR_RATE_T250_BER_DELTA	LESS THAN OR EQUAL TO	0.5	OCTUA/B,OEM1A/B/F	1	_IN_RANGE	EQUAL TO
P134_TA_DETCR_DETAIL_SUM_HD2_CO	MB						
0	MAX_AMP_WIDTH	LESS THAN	12000	OCE1,CTUA/B,OEM1A/B/F,STD	2	AMP7_CNT	GREATER THAN OR EQUAL TO
P2109_DFS_BER_STATS	SER	GREATER THAN OR EQUAL TO	3.5	OCE1	3		
P2109_DFS_BER_STATS	SER	GREATER THAN OR EQUAL TO	4.8	OCTUA/B,OEM1A/B/F,STD	3		
P051_ERASURE_BER	BITS_IN_ERROR_BER	GREATER THAN	2	OCTUA/B	4	NUM_WRT	EQUAL TO
P051_ERASURE_BER	OTF_BER	GREATER THAN	7	OCTUA/B	4	NUM_WRT	EQUAL TO
P135_AGC_BASELINE_JUMP	MAX_JUMP	LESS THAN	140	OCE1,CTUA/B,OEM1A/B/F,STD	5	ACTIVE_HEATER	EQUAL TO
P050_ENCROACH_BER	OTF_BER	GREATER THAN	7	OCTUA/B	6	TEST_TYPE	EQUAL TO
P_AFH_DH_BURNISH_CHECK	DELTA_BURNISH_CHECK	GREATER THAN	-12	OCE1/STD	7	ACTIVE_HEATER	EQUAL TO
P_AFH_DH_BURNISH_CHECK	DELTA_BURNISH_CHECK	GREATER THAN	-8	OCTUA/B,OEM1A/B/F	7	ACTIVE_HEATER	EQUAL TO
P050_ENCROACH_BER	BITS_IN_ERROR_BER	GREATER THAN	2.1	OCTUA/B	8	TEST_TYPE	EQUAL TO
P275_ZAP_AUDIT_STATS2	MAX_3SIGRRO	LESS THAN OR EQUAL TO	10	00EM1A	9		
P050_ENCROACH_BER	HARD_ERR_CNT	LESS THAN OR EQUAL TO	0	OCTUA/B	10	TEST_TYPE	EQUAL TO
P051_ERASURE_BER_DELTAS	OTF_BER_DELTA	LESS THAN	0.7	OCTUA/B	12	NUM_WRT_ERASURE	EQUAL TO
P107_UNVER_HD_TOTAL	UNVER	LESS THAN OR EQUAL TO	600000	OCTUA/B,OEM1A/B/F	12		
P_SETTLING_SUMMARY	HMS_CAP_1	GREATER THAN	1.5	OCE1,CTUA/B	13	WRT_CLRNC	EQUAL TO
P_SETTLING_SUMMARY	HMS_CAP_1	GREATER THAN OR EQUAL TO	1.3	OCTUA/B,OEM1A/B/F,STD	13		
P_SETTLING_SUMMARY	HMS_MRGN_1	GREATER THAN	0	OCE1,OEM1A/B/F	14	WRT_CLRNC	EQUAL TO
P_SETTLING_SUMMARY	HMS_MRGN_1	GREATER THAN	3.5	OCTUA/B	14	WRT_CLRNC	EQUAL TO
P_SETTLING_SUMMARY	DELTA_HMS_CAP_1	GREATER THAN	-1	OCTUA/B	15	WRT_CLRNC	EQUAL TO
_SETTLING_SUMMARY	DELTA_HMS_CAP_1	GREATER THAN	-0.7	OCTUA/B,OEM1A/B/F	15	WRT_CLRNC	EQUAL TO
_SETTLING_SUMMARY	DELTA_HMS_CAP_1	GREATER THAN OR EQUAL TO	-1.1	OCTUA/B,OEM1A/B/F	15	HMS_CAP_1	LESS THAN
P250_ERROR_RATE_BY_ZONE	RAW_ERROR_RATE	LESS THAN OR EQUAL TO	-1.8	00EM1A	16	SPC_ID	EQUAL TO
P134_TA_SUM_HD2	AMP7_CNT	LESS THAN OR EQUAL TO	10	OCTUA/B,OEM1A/B/F	17	AMP6_CNT	GREATER THAN
P2109_DFS_ERROR_STATS	ITRTN_ERR_CNT	LESS THAN OR EQUAL TO	550	OCE1,CTUA/B,OEM1A/B/F,STD	19		
P134_TA_DETCR_DETAIL	TA_SEVERITY	LESS THAN	5	35CE1,CTUA/B,OEM1A/B/F	20		
POSO_ENCROACH_BER_NATIVE	ONE_PLUS_ECC_CNT	LESS THAN	419000	OCTUA/B,OEM1A/B/F,STD	21	HARD_ERR_CNT	GREATER THAN OR EQUAL TO
P315_INSTABILITY_METRIC	HD_INSTABILITY_METRIC	LESS THAN	28	OCE1,CTUA/B,OEM1A/B/F,STD	22		TA INDESCRIPTION OF SECURITION
PO41_PES_SCREEN_MAX_VALS	MAX_PERCENT_DIFF_ID	LESS THAN	9.5	OCE1	23	MAX PERCENT DIFF MD	GREATER THAN OR EQUAL TO
P VBAR FORMAT SUMMARY	TPI MRGN	GREATER THAN OR EQUAL TO	-0.02	OCTUA	24	SPC ID	EQUAL TO
P_VBAR_FORMAT_SUMMARY	TPI_MRGN	GREATER THAN OR EQUAL TO	-0.03	OCTUB/OEM1A	24	SPC_ID	EQUAL TO
P051_ERASURE_BER	BITS_IN_ERROR_BER	GREATER THAN	1.9	00EM1A	25	NUM_WRT	EQUAL TO
P598_ZONE_XFER_RATE	MAX_TIME_PER_XFER	LESS THAN OR EQUAL TO	300000	OCTUA/B,OEM1A/B/F	25	DATA_ZONE	GREATER THAN OR EQUAL TO
P598_ZONE_XFER_RATE	RATIO	GREATER THAN OR EQUAL TO	0.5	OCTUA/B,OEM1A/B/F	25	DATA_ZONE	GREATER THAN OR EQUAL TO
P598_ZONE_XFER_RATE	CALC_RATE	GREATER THAN OR EQUAL TO	154	00EM1A	25	DATA_ZONE	EQUALTO
P2109_DFS_BER_STATS_2	STD_DEV_RBIT_SER	LESS THAN	0.45	OCE1,CTUA/B,OEM1A/B/F,STD	27		E-4-0-2
2103_010_021(_011110_2	010_021_1011_0211	2205 111111	0.10	0022/010/10/05/02/11/2/05/1/010	51		
P_SETTLING_TCS_SUM_COMBO	MIN_HMS_CAP_1	GREATER THAN OR EQUAL TO	1.92	OCTUA/B,OEM1A/B/F,STD	30	MEAN_HMS_CAP_COLD	LESS THAN
P134_TA_SUM_HD2	TA_CNT	LESS THAN OR EQUAL TO	130	OCE1,CTUA/B,OEM1A/B/F	31		
P2109_DFS_BER_STATS	SER	GREATER THAN OR EQUAL TO	3.2	OALL	99	42231	
P2109_DFS_BER_STATS	RRAW_BER	GREATER THAN OR EQUAL TO	2	OALL	99	48460	
PO51_ERASURE_BER	HARD_ERR_CNT	LESS THAN OR EQUAL TO	0	OALL	99	48585NUM_WRT	EQUAL TO
PO51_ERASURE_BER_DELTAS	OTF_BER_DELTA	LESS THAN OR EQUAL TO	2.1	OALL	99	14188NUM_WRT_ERASURE	EQUAL TO
PO51_ERASURE_BER_DELTAS	OTF_BER_DELTA	LESS THAN	2	OALL	99	14188TRK_INDEX	GREATER THAN
POS1_ERASURE_BER_DELTAS	OTF_BER_DELTA	LESS THAN	2	OALL	99	14188TRK_INDEX	LESS THAN
315_INSTABILITY_METRIC	HD_INSTABILITY_METRIC	LESS THAN OR EQUAL TO	38	OALL	99	48455	ELSS THAIN
	- Val	LESS THAN OR EQUAL TO	2	OALL	99		
P150_GAIN_SUM_DELTA	MAX_CORR_GAIN_DELTA DETCR_RESISTANCE	GREATER THAN	40	OALL	99	48446	EQUAL TO
P186_DETCR_RES		LESS THAN	160	OALL	99	48629SPC_ID	
P186_DETCR_RES	DETCR_RESISTANCE	CONTROL OF THE CONTRO		Calculation	1900	48629DETCR_RESISTANCE	GREATER THAN
P186_DETCR_RES	BIAS_CURRENT	GREATER THAN	0	OALL	99	48629SPC_ID	EQUAL TO
P025_LOAD_STAT	LOAD_PEAK_CUR	LESS THAN	10	OALL	99	10279STAT_NAME	EQUAL TO

caBP200Customer5Tab1/Testing128

Product	Tab Cust	tomer 🔼	TGTA	▼ TGTP	твтс	lec l	Failure Cause
Grenada Bl	2 700 Apple	е	G2AED3006.APD1.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	701 Apple	e FFS	G2AED3001.APD2.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	740 Dell		G2AED3006.CCD4.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	760 Fujits	su	G2AED3006.CCD4.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	20 HP		G2AED3006.HPD1.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	EC 10854 Sense Data returned are not expected	d F3/ PF3
	541 Leno	OVO	G2AED3006.CCD6.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	230 Sam	sung	G2AED3006.CCD4.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	232 Siem	nens	G2AED3006.CCD4.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	300 STD	DISTI	G2AED3006.CCD4.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	500 STD	OEM	G2AED3006.CCD4.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
	900 CTU		G2AED3006.CCD4.AADN00.ZZZZ	G2AED30ZZ.SDP1.AADN00.ZZZZ	G2AED30ZZ.BRNB.AADN00.ZZZZ	N/A	
Bacall BP:	2 160 MOT	OROLA	B2AED3006.SDC1.AADE00.ZZZZ	B2AED30ZZ.SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	N/A	
	115 SHAI	RP	B2AED3006.RPC1.AADE00.ZZZZ	B2AED30ZZ SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	N/A	
	671 THO	MSON	B2AED3006.SDC1.AADE00.ZZZZ	B2AED30ZZ SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	N/A	
	852 SON	Y EVAL	B2AED3006.NYC1.AADE00.ZZZZ	B2AED30ZZ.SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	N/A	
	ECH	IOSTAR				EC 10648 Fail to get HDA Serial Number or HDA	A
	262 TEC	HNOLOGY	B2AED3006.SDC1.G101DE.ZZZZ	B2AED30ZZ SDP1.G101DE.ZZZZ	B2AED30ZZ.BRNB.G101DE.ZZZZ	SN mismatch on reFIN	PF3
	PAN	ASONIC					
	635 EVA	L	B2AED3006.MAC1.AADE00.ZZZZ	B2AED30ZZ SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	N/A	
	300 STD		B2AED3006.SDC1.AADE00.ZZZZ	B2AED30ZZ.SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	N/A	
	500 STD	OEM	B2AED3006.SDC1.AADE00.ZZZZ	B2AED30ZZ.SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	N/A	
	900 CTU	EVAL	B2AED3006.SDC1.AADE00.ZZZZ	B2AED30ZZ.SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	N/A	
	125 PAN	IASONIC	B2AED3006.MAC1.AADE00.ZZZZ	B2AED30ZZ.SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	14761-Failed CSetDriveConfigAttributes	DCM
	509 STD	OEM	B2AED3006.SDC1.AADE00.ZZZZ	B2AED30ZZ.SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	14761-Failed CSetDriveConfigAttributes	DCM
	141 SON	IY:	B2AED3006.NYC1.AADE00.ZZZZ	B2AED30ZZ.SDP1.AADE00	B2AED30ZZ.BRNB.AADE00	14761-Failed CSetDriveConfigAttributes	DCM

- 1. GBP2 HP, this item task for PCO 5. Issue exists on CPC and SIC. SPT process is working. ECD 1/31/14
- 2. BBP2, Echostar, is working on the branch for PCO 4.3, and official fix on TIPS and PCO 5. ECD 1/31/14
- 3. BBP2, Panasonic/Sony/STD OEM. These failures are not process code related, once we have the ECR submitted to fix CCAs and implemented in DCM, this error will disappear.

- SPC ID is a test parameter used to differentiate between test calls and tables
- There is no clearly defined set of rules to assigning SPC ID but in general, PRE2 should use a range of 10000-19999, CAL2 should use 20000-29999, FNC2 is 30000-39999 and FIN2 is 40000+
- Many test calls don't need a specific SPC ID, so those default to either 1, 0 or 'None'
- Main use is to filter on SPC_ID when applying GOTF criteria, see below

113003

113004

```
<row>
   <Criteria_Table>P_VBAR_FORMAT_SUMMARY
   <Criteria Column>TPI MRGN</Criteria Column>
                                                           32827
   <Criteria Op>GREATER THAN OR EQUAL TO</Criteria Op>
    <Criteria Value>-0.02</Criteria Value>
                                                           32830
    <Num Violations>0</Num Violations>
                                                           32831
   <Business Group>CTUA</Business Group>
   <Grade Position>24</Grade Position>
   <Grade Level>1</Grade Level>
   <Filter1 Item>SPC ID</Filter1 Item>
   <Filter1 Op>EQUAL TO</Filter1 Op>
                                                           112999
   <Filter1 Value>20500</Filter1 Value>
                                                           113000 P VBAR FORMAT SUMMARY:
 </row>
                                                           113001 HD PHYS PSN DATA ZONE HD LGC PSN BPI CAP BPI INTERPOLATED BPI PICK BPI MRGN
                                                           113002
```

```
32825 Jan 03 2014-00:11:21 Parameters==> ([0, 0, 0, 0], [],)
32826 Jan 03 2014-00:11:21 **SPC ID32=20000 CMT=None
32828 P VBAR FORMAT SUMMARY:
32829 HD PHYS PSN DATA ZONE HD LGC PSN BPI CAP BPI INTERPOLATED BPI_PICK BPI_MRGN
112997 Jan 03 2014-05:09:58 Parameters==> ([0, 0, 0, 0], [],)
112998 Jan 03 2014-05:09:58 **SPC_ID32=20500 CMT=None
```

0 0.8527

0 0.9795

0 0.9942




0.7997

0.9484

0.053


0.0458

TCG Self 3 E-10-0123/psting -- D15ive (SED) Paroseess Flow





Grenada^{ca}Bap-2-0052500 (Bit 14-ielid 01/12/14e nad 9 of 128




94% yield. achieved budget.

No gap to BP.

Grenada 500GB Prime yield	MAT1.0	MAT2.0	CRT1.0	WW22	WW23	WW24	WW25	WW26	WW27	WW28	WW29	WW30
Phase/PCO	N/A	GB2_03_1	GB2_04_1	GB2_04_2					GB2_04_3			
Actual (Korat)	N/A	94.4%	93.9%	LV	LV	93.1%	LV	LV	LV			
Volume	N/A	1001	328	LV	LV	4853	LV	LV	LV			
Actual (Wuxi)			94.2%	LV	LV	LV	LV	LV	LV			
Volume			263	LV	LV	LV	LV	LV	LV			
Actual (Suzhou)			NA	LV	LV	LV	LV	LV	LV			
Volume			NA	LV	LV	LV	LV	LV	LV			
Cum Yld (all)			94.1%	LV	LV	LV	LV	LV	LV			
Volume			591	LV	LV	LV	LV	LV	LV			
Budget	87.1%	87.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%	89.1%

Grenada^{Ca}B³D-2-00523 JCs Bock/feites Fleet Call Page 80 of 128




93% yield. achieved budget.

0.6% gap to BP

Grenada 1TB Prime yield	MAT1.0	MAT2.0	CRT1.0	WW22	WW23	WW24	WW25	WW26	WW27	WW28	WW29	WW30
Phase/PCO	GB2_02_2	GB2_03_1	GB2_04_1	GB2_04_2					GB2_04_3			
Actual (Korat)	90.9%	91.2%	90.6%	LV	LV	92.3%	89.1%	LV	93.0%			
Volume	778	379	452	LV	LV	5144	992	LV	1286			
Actual (Wuxi)				LV	LV	LV	LV	LV	LV			
Volume				LV	LV	LV	LV	LV	LV			
Actual (Suzhou)				LV	LV	LV	LV	LV	LV			
Volume				LV	LV	LV	LV	LV	LV			
Cum Yld (all)				LV	LV	LV	LV	LV	LV			
Volume				LV	LV	LV	LV	LV	LV			
Budget	89.6%	89.6%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%	92.7%

Yield Loss	Failure Causes	Status
1.30%	HEAD INSTABILITY_METRIC > 28 or 38	(a) GOTF spec refinements in PCO 5.0 to recovery 30 to 40% (b) investigate by TIMO (90x were ship to RHO on W1428) to try with new Stability2.0 test suit,
1.20%	AFH related tails. Drimary symptom are from ID roll off due to	Special builds with 4 legs, between MPT/NHK, TK/PNG slider/ Also add BP to be control to identify where the problem was from.
0.40%	Blister defect from wash process	TCL180 detergent to reduce this. 100% phase in by JAN
0.20%	Apple Bluenun scan failure	Allow downgrade to other OEM or Disty in PCO 5.0

Grenada^{Ca}B³D-2-005232^C Bockment of Page 81 of 128




88.8% yield. 1.9% below budget.

3.7% gap to BP

Grenada 2TB/4H Prime yield	MAT1.0	MAT2.0	CRT1.0	WW22	WW23	WW24	WW25	WW26	WW27	WW28	WW29	WW30
Phase/PCO	GB2_02_2	GB2_03_1	GB2_04_1	GB2_04_2					GB2_04_3			
Actual (Korat)	87.6%	87.5%	86.5%	86.5%	89.8%	91.4%	89.8%	LV	88.8%			
Volume	766	405	727	1004	2979	1958	1454	LV	3986			
Actual (Wuxi)												
Volume												
Actual (Suzhou)												
Volume												
Cum Yld (all)												
Volume												
Budget	86.6%	86.6%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%	90.7%

Yield Loss	Failure Causes	Status
1.80%	HEAD INSTABILITY_METRIC > 28 or 38	(a) GOTF spec refinements in PCO 5.0 to recovery 30 to 40% (b) investigate by TIMO (90x were ship to RHO on W1428) to try with new Stability2.0 test suit,
1.50%	INFH related tails. Drimary symptom are from ID roll off due to	Special builds with 4 legs, between MPT/NHK, TK/PNG slider/ Also add BP to be control to identify where the problem was from.
0.90%	EC10414 PRE2: found damage on Spacer issue	Working with SQE to get the closure

Grenada^{Ca}B³D-2-00523^{Ca}Bock/feite^A Fleet On 128 Page 82 of 128





88.7% yield. 0.1% below budget.


1.5% gap to BP


Grenada 3TB Prime yield	MAT1.0	MAT2.0	CRT1.0	WW22	WW23	WW24	WW25	WW26	WW27	WW28	WW29	WW30
Phase/PCO	GB2_02_2	GB2_03_1	GB2_04_1	GB2_04_2					GB2_04_3			
Actual (Korat)	80.7%	84.2%	82.8%	88.5%	86.5%	LV	80.7%	LV	88.7%			
WTF ratio (Korat)	0.3%	0.0%	0.0%	0.1%	0.1%	LV	0.5%	LV	0.0%			
Volume	910	236	642	913	1989	LV	1518	LV	1986			
Actual (Wuxi)												
WTF ratio (Wuxi)												
Volume												
Actual (Suzhou)												
WTF ratio (Suzhou)												
Volume												
Cum Yield (all)												
Volume												
Budget	84.4%	84.4%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%	88.8%

Yield Loss	Failure Causes	Status
2.00%	HEAD INSTABILITY_METRIC > 28 or 38	(a) GOTF spec refinements in PCO 5.0 to recovery 30 to 40% (b) investigate by TIMO (90x were ship to RHO on W1428) to try with new Stability2.0 test suit,












Current MBS for Grenadae and Bacall BR2

MS1407B0	Q3FY2014	Q4FY2014	Q1FY2015	Q2FY2015	Q3FY2015
GrenadaBP2 500GB	27,495	700,000	700,000	700,000	700,000
GrenadaBP2 1.0TB	715,699	1,567,482	3,430,469	4,637,012	4,458,076
GrenadaBP2 2.0TB	525,579	1,629,783	2,212,681	2,792,963	2,621,245
GrenadaBP2 3.0TB	177,560	557,192	926,000	991,434	948,314
GrenadaBP2 Total	1,418,838	3,754,457	6,569,150	8,421,409	8,027,635

MS1407B0	Q3FY2014	Q4FY2014	Q1FY2015	Q2FY2015	Q3FY2015
BacallBP2 1.0TB		547,034	1,375,255	1,630,879	1,630,879
BacallBP2 2.0TB	23,000	575,483	982,162	983,559	983,866
BacallBP2 3.0TB		204,499	265,848	265,848	265,848
BacallBP Total	23,000	1,327,016	2,623,265	2,880,286	2,880,593

Grenada:BR-20:52ustomen Qualification:Schedules




Apple: STX communicated in August '13 that BP2 must be qualified by end of June to maintain supply continuity. Apple has still not agreed to this schedule.

Dell: have changed to quarterly block schedule, BP2 falls into CQ3 RTS block.

Lenovo: pulling for early start. Will ship CTUs concurrently with Lenovo EST testing.

<u>HP</u>: Schedule underpinned. March start due to OEM RDT completion in Feb. CTUs ship late Feb.





BP2 RDT 400K Demo - On track for ~Mid Jan '14

DVR - Jan 15 Humax 2TB units to hold qualification slot; Jan 31 BSKYB 1TB units to meet system schedule

NAS – Gated by Rapid RAID Rebuild functionality and performance test comparisons across segments; Plan to close this feature and it's testing inside Jan '14

SV - Apr 1 (external); Internal dates to be solidified by PLM/DE team ASAP



Grenada BP2 Assumptions

Lombard 4TB 8/4, no 3TB KV waterfall; drive waterfall to Lombard 3TB

Drive yields per core team: Based on Lombard 8/4 CMC projections

- ET Yields per core team: Based on Lombard CMC Projections
- Media Yields per Nov CMC: Based on Lombard CMC Projections

WRR

- BOM per Lombard 8H CMCs, with the added costs for KV PCBA
- Volumes per PLM

Materials Detail:										
	GBP 1TB 2H	GBP 1TB 2H	GBP 1TB 2H	GBP2 1TB 2H	GBP2 1TB 2H	GBP2 1TB 2H	Delta	Delta	Delta	
	Qtr3-14	Qtr4-14	Qtr1-15	Qtr3-14	Qtr4-14	Qtr1-15	Qtr3-14	Qtr4-14	Qtr1-15	Comments
Total MBA	\$4.07	\$4.05	\$4.05	\$4.07	\$4.05	\$4.05	\$0.00	\$0.00	\$0.00	
HSA	\$5.63	\$5.59	\$5.63	\$5.76	\$5.71	\$5.74	(\$0.13)	(\$0.12)	(\$0.11)	
PCCA - LOH	\$0.42	\$0.41	\$0.41	\$0.48	\$0.47	\$0.47	(\$0.07)	(\$0.06)	(\$0.06)	reset new PN
Connector-PCCA	\$0.14	\$0.14	\$0.14	\$0.13	\$0.13	\$0.12	\$0.01	\$0.01	\$0.01	
Flex	\$0.44	\$0.43	\$0.43	\$0.52	\$0.51	\$0.51	(\$0.08)	(\$0.08)	(\$0.08)	reset new PN
Preamp	\$0.63	\$0.63	\$0.63	\$0.59	\$0.58	\$0.57	\$0.04	\$0.05	\$0.06	Lombard PreAmp
Suspension Assembly	\$1.41	\$1.40	\$1.40	\$1.45	\$1.44	\$1.44	(\$0.04)	(\$0.04)	(\$0.04)	reset new PN
HDA	\$3.52	\$3.51	\$3.51	\$3.45	\$3.37	\$3.36	\$0.07	\$0.14	\$0.15	
Cover	\$0.85	\$0.84	\$0.84	\$0.79	\$0.71	\$0.70	\$0.06	\$0.13	\$0.14	304SS vs 430 SS
PCBA Foam	\$0.01	\$0.01	\$0.01	\$0.00	\$0.00	\$0.00	\$0.01	\$0.01	\$0.01	00100 10 100 00
PCBA	\$7.72	\$7.61	\$7.54	\$7.42	\$7.30	\$7.23	\$0.30	\$0.31	\$0.31	
Flash	\$0.15	\$0.15	\$0.15	\$0.19	\$0.18	\$0.18	(\$0.03)	(\$0.03)	(\$0.03)	
Controller	\$3.81	\$3.74	\$3.67	\$3.55	\$3.48	\$3.41	\$0.26	\$0.26	\$0.26	LuxorLite vs Luxsor
Discrete	\$0.21	\$0.21	\$0.21	\$0.16	\$0.16	\$0.16	\$0.05	\$0.05	\$0.05	Edworette va Edward
PCB	\$0.66	\$0.64	\$0.64	\$0.66	\$0.64	\$0.64	(\$0.00)	\$0.00	\$0.00	
Sensor-PCBA	\$0.13	\$0.13	\$0.13	\$0.10	\$0.10	\$0.10	\$0.03	\$0.03	\$0.03	
Total Mtrl BOM	\$20.95	\$20.76	\$20.73	\$20.71	\$20.44	\$20.38	\$0.24	\$0.32	\$0.34	BOM reduction for GBP2
Total Scrap	\$0.83	\$0.72	\$0.70	\$0.90	\$0.79	\$0.75	(\$0.07)	(\$0.07)	(\$0.05)	
Total Warranty	\$0.73	\$0.70	\$0.70	\$2.66	\$1.74	\$1.19	(\$1.94)	(\$1.04)	(\$0.49)	Jan CMC Warranty reduction:
Drive Freight	\$0.66	\$0.62	\$0.58	\$0.66	\$0.62	\$0.58	\$0.00	\$0.00	(\$0.00)	•
Total TVC	\$23.18	\$22.81	\$22.72	\$24.95	\$23.60	\$22.92	(\$1.77)	(\$0.79)	(\$0.19)	
Total TVC adj w/o WRR							\$0.17	\$0.25	\$0.30	
Total TVO day W/O Will							VV. 17	VV.20	ψ0.50	



	GBP 2TB 4H	GBP 2TB 4H	GBP 2TB 4H	GBP2 2TB 4H	GBP2 2TB 4H	GBP2 2TB 4H	Delta	Delta	Delta	
	Qtr3-14	Qtr4-14	Qtr1-15	Qtr3-14	Qtr4-14	Qtr1-15	Qtr3-14	Qtr4-14	Qtr1-15	Comments
Total MBA	\$4.77	\$4.75	\$4.73	\$4.77	\$4.77	\$4.75	\$0.00	(\$0.02)	(\$0.02)	
Motor	\$2.27	\$2.27	\$2.25	\$2.27	\$2.29	\$2.27	\$0.00	(\$0.02)	(\$0.02)	
HSA	\$7.55	\$7.49	\$7.48	\$7.73	\$7.66	\$7.65	(\$0.19)	(\$0.17)	(\$0.17)	
PCCA - LOH	\$0.42	\$0.42	\$0.42	\$0.48	\$0.48	\$0.48	(\$0.06)	(\$0.06)	(\$0.06)	New PN reset
Flex	\$0.54	\$0.54	\$0.54	\$0.67	\$0.65	\$0.65	(\$0.13)	(\$0.11)	(\$0.11)	
Preamp	\$0.83	\$0.83	\$0.83	\$0.75	\$0.74	\$0.74	\$0.08	\$0.09	\$0.09	Lombard PreAmp
Suspension Assembly	\$2.82	\$2.80	\$2.80	\$2.90	\$2.89	\$2.88	(\$0.08)	(\$0.09)	(\$0.09)	New PN reset
HDA	\$5.13	\$5.12	\$5.12	\$5.01	\$4.93	\$4.91	\$0.13	\$0.19	\$0.21	additional \$0.23 with PDSP
Cover	\$0.85	\$0.84	\$0.84	\$0.79	\$0.71	\$0.70	\$0.07	\$0.13	\$0.14	304SS vs 430 SS
Disc Clamp	\$0.42	\$0.42	\$0.42	\$0.36	\$0.36	\$0.35	\$0.06	\$0.06	\$0.07	Lombard clamp
PCBA Foam	\$0.01	\$0.01	\$0.01	\$0.00	\$0.00	\$0.00	\$0.01	\$0.01	\$0.01	
PCBA	\$7.72	\$7.61	\$7.54	\$7.42	\$7.30	\$7.23	\$0.30	\$0.31	\$0.31	
Flash	\$0.15	\$0.15	\$0.15	\$0.19	\$0.18	\$0.18	(\$0.03)	(\$0.03)	(\$0.03)	4M to 8M flash
Controller	\$3.81	\$3.74	\$3.67	\$3.55	\$3.48	\$3.41	\$0.26	\$0.26	\$0.26	LuxorLite vs Luxsor
Discrete	\$0.21	\$0.21	\$0.21	\$0.16	\$0.16	\$0.16	\$0.05	\$0.05	\$0.05	
Sensor-PCBA	\$0.13	\$0.13	\$0.13	\$0.10	\$0.10	\$0.10	\$0.03	\$0.03	\$0.03	
Total Mtrl BOM	\$25.18	\$24.97	\$24.87	\$24.94	\$24.66	\$24.55	\$0.24	\$0.31	\$0.33	BOM reduction for GBP2
Total Scrap	\$2.86	\$2.77	\$2.64	\$2.46	\$2.40	\$2.53	\$0.40	\$0.37	\$0.11	
Total Warranty	\$0.97	\$0.95	\$0.94	\$3.03	\$2.00	\$1.56	(\$2.05)	(\$1.05)	(\$0.61)	
Drive Freight	\$0.78	\$0.73	\$0.69	\$0.78	\$0.73	\$0.69	\$0.00	(\$0.00)	(\$0.00)	
Total TVC	\$29.82	\$29.44	\$29.17	\$31.23	\$29.81	\$29.35	(\$1.42)	(\$0.37)	(\$0.17)	
Total TVC adj w/o WRR							\$0.64	\$0.68	\$0.44	





									\$0.49	
Total TVC	\$33.96	\$33.38	\$33.32	\$36.56	\$34.56	\$33.67	(\$2.60)	(\$1.18)	(\$0.35)	
Drive Freight	\$0.80	\$0.75	\$0.71	\$0.80	\$0.75	\$0.71	(\$0.00)	(\$0.00)	(\$0.00)	
Total Warranty	\$1.08	\$1.04	\$1.04	\$3.69	\$2.48	\$1.88	(\$2.62)	(\$1.44)	(\$0.84)	
Total Scrap	\$3.34	\$3.07	\$3.16	\$3.57	\$3.04	\$2.90	(\$0.22)	\$0.03	\$0.26	
Total Mtrl BOM	\$28.70	\$28.48	\$28.38	\$28.47	\$28.25	\$28.14	\$0.24	\$0.23	\$0.24	BOM reduction for GBP2
Sensor-PCBA	\$0.13	\$0.13	\$0.13	\$0. <mark>1</mark> 0	\$0.10	\$0.10	\$0.03	\$0.03	\$0.03	
Discrete Sensor DCRA	\$0.21	\$0.21	\$0.21	\$0.16	\$0.16	\$0.16	\$0.05	\$0.05	\$0.05	
Controller	\$3.81	\$3.74	\$3.67	\$3.55	\$3.48	\$3.41	\$0.26	\$0.26	\$0.26	LuxorLite vs Luxsor
Flash	\$0.15	\$0.15	\$0.15	\$0.19	\$0.18	\$0.18	(\$0.03)	(\$0.03)	(\$0.03)	4M to 8M flash
PCBA	\$7.72	\$7.61	\$7.54	\$7.42	\$7.30	\$7.23	\$0.30	\$0.31	\$0.31	414 . 014 7 . 1


PCBA Foam	\$0.01	\$0.01	\$0.01	\$0.00	\$0.00	\$0.00	\$0.01	\$0.01	\$0.01	
Disc Clamp	\$0.42	\$0.42	\$0.42	\$0.36	\$0.36	\$0.35	\$0.06	\$0.06	\$0.06	Lombard clamp
Cover	\$1.40	\$1.39	\$1.39	\$1.26	\$1.25	\$1.25	\$0.14	\$0.14	\$0.14	304SS vs 430 SS
HDA	\$6.40	\$6.39	\$6.39	\$6.20	\$6.18	\$6.18	\$0.20	\$0.20	\$0.21	additional \$0.46 with PDSP
Suspension Assembly	\$4.24	\$4.20	\$4.19	\$4.35	\$4.33	\$4.33	(\$0.11)	(\$0.13)	(\$0.13)	New PN reset
Preamp	\$1.12	\$1.12	\$1.12	\$1.07	\$1.06	\$1.06	\$0.05	\$0.06	\$0.06	Lombard PreAmp
Flex	\$0.58	\$0.57	\$0.57	\$0.71	\$0.70	\$0.70	(\$0.14)	(\$0.13)	(\$0.13)	New PN reset
PCCA - LOH	\$0.42	\$0.42	\$0.42	\$0.48	\$0.48	\$0.48	(\$0.06)	(\$0.06)	(\$0.06)	New PN reset
HSA	\$9.51	\$9.43	\$9.43	\$9.77	\$9.69	\$9.69	(\$0.26)	(\$0.26)	(\$0.26)	
IVIOLOI	ΨZ.Z1	ΨΖ.ΖΙ	ΨΖ.Ζ3	\$2.27	\$2.29	\$2.27	\$0.00	(\$0.02)	(\$0.02)	Dalarice leature
Total MBA Motor	\$5.08 \$2.27	\$5.05 \$2.27	\$5.03 \$2.25	\$5.08	\$5.07	\$5.05	\$0.00 \$0.00	(\$0.02)	(\$0.02)	Balance feature
T-4-LMDA	Qtr3-14	Qtr4-14	Qtr1-15	Qtr3-14	Qtr4-14	Qtr1-15	Qtr3-14	Qtr4-14	Qtr1-15	Comments
	GBP 3TB 6H	GBP 3TB 6H	GBP 3TB 6H	GBP2 3TB 6H			Delta	Delta	Delta	^ -



HIGHLY CONFIDENTIAL








Grenada BP2 Plastic DSP Saving Projections Filed 01/12/18 Page 95 of 128

MS1407A0	Capacity	Q3FY2014	Q4FY2014	Q1FY2015	Q2FY2015	Q3FY2015
GRENADABP2	500	26,195	699,998	700,000	700,000	700,000
	1,000	601,100	1,567,482	3,430,469	4,637,012	4,458,076
	2,000	478,282	1,629,783	2,212,681	2,792,963	2,621,245
	3,000	184,560	557,192	926,000	991,434	948,314

- Plastic DSP current saving is \$0.23, expect to erode savings to \$0.20 for additional process cleaning.
- One DSP in 2TB, and two DSP's in the 3TB.

	Q314	Q414	Q115	Q215	Q315	Total
2TB	478282	1629783	2212681	2792963	2621245	9734954
3TB	184560	557192	926000	991434	948314	3607500
1 DSP	0.2	0.2	0.2	0.2	0.2	0.2
2 DSP	0.4	0.4	0.4	0.4	0.4	0.4
2TB Savings	\$95,656.40	\$325,956.60	\$442,536.20	\$558,592.60	\$524,249.00	\$1,946,990.80
3TB Savings	\$73,824.00	\$222,876.80	\$370,400.00	\$396,573.60	\$379,325.60	\$1,443,000.00

- Total 5 Quarter saving on 2TB is ~\$1.95 Million
- Total 5 Quarter saving on 3TB is ~\$1.45 Million
- Total 5 Quarter programs savings is ~\$3.4 Million



Grenada / Bacall BP2 CTU / SAD Readiness - Materials



January 13, 2014 Bob Kolanda

MS1407B0 Grenada / Bacall Demand outlook:

MS1407B0	Q3FY2014	Q4FY2014	Q1FY2015	Q2FY2015	Q3FY2015
GrenadaBP2 500GB	27,495	700,000	700,000	700,000	700,000
GrenadaBP2 1.0TB	715,699	1,567,482	3,430,469	4,637,012	4,458,076
GrenadaBP2 2.0TB	525,579	1,629,783	2,212,681	2,792,963	2,621,245
GrenadaBP2 3.0TB	177,560	557,192	926,000	991,434	948,314
GrenadaBP2 Total	1,418,838	3,754,457	6,569,150	8,421,409	8,027,635
MS1407B0	Q3FY2014	Q4FY2014	Q1FY2015	Q2FY2015	Q3FY2015
BacallBP2 1.0TB	1=	547,034	1,375,255	1,630,879	1,630,879
BacallBP2 2.0TB	23,000	575,483	982,162	983,559	983,866
BacallBP2 3.0TB	a.	204,499	265,848	265,848	265,848
BacallBP Total	23,000	1,327,016	2,623,265	2,880,286	2,880,593

- **CTU Bag of Parts Critical items:**
- MBA Nidec NCCP / Nidec Th, SemKorat, MD balance capable + Option 3 samples on Nidec
- Media RMO 10.5B+ / 9LT + ODM 9LT versions, LIM and MIM, no Showa
- **Plastic DSP** Hi P planned for non Apple CTU. Using dbbl seal version to minimize particle failures
- 430SS Top Cover Seksun Ch and Thailand. 304SS not included, removed from BOM
- Clamp Lombard version 1 for MD balance capable Grenada and Bacall. Version 2 in qual now. Bacall BP2 issue mitigated with Consign HGA only in CTU.
- Stack / Wafer 100% uPemto, RHO NRM and Springtown / Consigned TDK, RHO includes bar bake
- TGA / Suspension 11.3.1 / NHK and MPT versions allowed
- **Pre amp –** LSI and TI all configurations. No restrictions
- **PCBA** ST and TI Dillon (TI version 4.2 qualified in CRT1 on both Grenada and Bacall BP2)
- DDR No shrink parts included 96

Materials 3:16-cy-00523-JCS Document 155-5 Filed 01/12/18 Page 98 of 128

- Volume Ramp Bag of Parts:
- MBA Same as CTU, Option 3 Nidec (end plate material change for DPPM improvement) in Qual, ECD mid February, implementation start in FQ4
- Media Same as CTU, Showa currently a BP1 item. No near term plans for qual
- Plastic DSP:
- Hi P 4 cavities conditionally approved. Volume implementation pending cleanliness improvements to address NMD failures seen in CRT1. DC working with Hi P for viable volume solution. ECD for volume by end
- FEP No 1st article approvals. Target FQ3 for 1st article, FQ4 for demonstrated cleanliness and approval. Likely ramp beginning FQ1'15
- "Common" BOM HDA items Common to BP1, fully approved
- 430SS Top Cover Seksun Ch fully approved. MMI Ch qual in Feb, MMI qual in FQ4
- Lombard Clamp Version 2 in Qual, ECD full approval with all 3 suppliers by mid February.
- Stack / Wafer Same as CTU, for Bacall BP2 Ramp add RHO with completion of Lombard clamp qual
- TGA / Suspension Same as CTU. 11.3.1 / NHK and MPT versions allowed
- Hook up / PCCA / PCC Current status included. All subcon items planned for full approval with completion of CRT2 in February.
- · Electrical:
- Preamp all configurations / TI and LSI are approved.
- Luxor lite LSI single sourced, TSMC 14 fully approved
- ST Dillon M5 and Agrate fully qualified
- TI Dillon Volume usage pending resolution and qual for Bridging, Modulation and Vcore issues. Lead frame change samples due in March, passive changes and likely Servo FW revisions required for other issues. Full qual ECD by end FQ2'15
- DDR Shrinks Samples in FQ3 on Samsung, Hynix and Nanya. Qual and release to OEMs in FQ4
- **Elash** Elite disqualified, no sample dates for re qual. Add Micron for qual with DDR.

Key Materials tems 12 Remaining Flu 7 PCC quals

Part # 1D	ASL	WW28	WW32	Comments / Actions
100713905 Mektec SZ PCCA LSI	P		Target Full	Pending CRT2 Reli Completion
100716580 Mektec SZ PCCA TI	Р		Target Full	Pending CRT2 Reli Completion
2D				
100717875 BEW HU LSI	AE		Target Full	Pending CRT2 Reli Completion
100724673 BEW HU TI	AE	Leverage AS from 100717875	Target Full	Pending CRT2 Reli Completion
100713907 BEW PCCA LSI	AE		Target Full	Pending CRT2 Reli Completion
100716583 BEW PCCA TI	AE	Leverage AS from 100713907	Target Full	Pending CRT2 Reli Completion
100713907 Mektec SZ PCCA LSI	Р	Leverage AS from 100716583	Target Full	Pending CRT2 Reli Completion
100716583 Mektec SZ PCCA TI	Р		Target Full	Pending CRT2 Reli Completion
100713907 Mektec Th PCCA LSI	AE	Leverage AS from 100716583	Target Full	Pending CRT2 Reli Completion
3D				
100721737 BEW PCCA LSI	AE	Leverage AS 100728025	Target Full	Pending CRT2 Reli Completion
100728076 BEW PCCA TI	AE		Target Full	Pending CRT2 Reli Completion
100729824 CPT HU LSI	AE	Leverage AS 100729825	Target Full	Pending CRT2 Reli Completion
100729824 CPW HU LSI	AE	WUGGD41189A - CRT2	Towart Full	No clear indication of fault cause,
100723624 CPW HU LSI	AE	WUGGD41189A - CK12	Target Full	combination included in CRT2
100729825 CPW HU TI	AE	Full will leverage 100729824 as AS	Target Full	
100721737 Mektec SZ PCCA LSI	Р		Target Full	Pending CRT2 Reli Completion
100728076 Mektec SZ PCCA TI	Р		Target Full	Pending CRT2 Reli Completion

Page

98

© Seagate Confidential

Key Materials Items – Post SAD items

P/N	Supplier (SSP)	Target Qual	Actions, Owners, Dates to Closure					
100660334	SEIKO INSTRUMENTS (THAILAND) GATEWAY	Post SAD - February	Pending 1st article submittal for Auto Line					
100713905	MEKTEC NPCT - PCCA 1D LSI	Post SAD - Feb / March	New Supplier Site					
100713906	MEKTEC NPCT - PCC 1D	Post SAD - Feb / March	New Supplier Site					
100713907	MEKTEC NPCT - PCCA 2D LSI	Post SAD - Feb / March	New Supplier Site					
100713909	MEKTEC NPCT - PCC 2D	Post SAD - Feb / March	New Supplier Site					
100716580	MEKTEC NPCT - PCCA 1D TI	Post SAD - Feb / March	New Supplier Site					
100716583	MEKTEC NPCT - PCCA 2D TI	Post SAD - Feb / March	New Supplier Site					
100717977	FUJIKURA ELECTRONICS THAI LTD - LSI	Post SAD - March	SWOT Resolution, RGA WW33					
100721737	MEKTEC NPCT - PCCA 3D LSI	Post SAD - Feb / March	New Supplier Site					
100721739	MEKTEC NPCT - PCC 3D LSI	Post SAD - Feb / March	New Supplier Site					
100724787	FUJIKURA ELECTRONICS THAI LTD - TI	Post SAD - March	SWOT Resolution, RGA WW33					
100728076	MEKTEC NPCT - PCCA 3D TI	Post SAD - Feb / March	New Supplier Site					
100728078	MEKTEC NPCT - PCC 3D TI	Post SAD - Feb / March	New Supplier Site					
100729251	SEIKO INSTRUMENTS (THAILAND) GATEWAY	Post SAD - January	Pending 1st article submittal for Auto Line					
100738738	NIDEC RANGSIT FACTORY (NIRT), Option 3	Post SAD - February	End Cap Change for DPPM Improvement					
100738739	NIDEC ZHEJIANG CORP (NIPC), Option 3	Post SAD - February	End Cap Change for DPPM Improvement					
100738740	NIDEC RANGSIT FACTORY (NIRT) Option 3	Post SAD - February	End Cap Change for DPPM Improvement					
100738741	NIDEC ZHEJIANG CORP (NIPC) Option 3	Post SAD - February	End Cap Change for DPPM Improvement					
100738836	NIDEC RANGSIT FACTORY (NIRT) Option 3	Post SAD - February	End Cap Change for DPPM Improvement					
100738837	NIDEC ZHEJIANG CORP (NIPC) Option 3	Post SAD - February	End Cap Change for DPPM Improvement					
703518200	SEIKO INSTRUMENTS (THAILAND) GATEWAY	Post SAD - January	Pending 1st article submittal for Auto Line					
707647900	Hi-P - Plastic DSP	Post SAD - March	Approvals pending cleanliness improvements					
707647900	FEP - Plastic DSP	Post SAD - June	Approvals pending cleanliness improvements					

Page

© Seagate Confidential

Key Materials Items – AMLR Status / Filed 01/12/18 Page 101 of 128

AMLR Summary per SSP

Total Items Tracked = 309

- •Currently @ AB / AD / AS = 292 / 94%
- •Currently @ AE = 11 / 4%
- •Currently @ P = 6 / 2%
- •Post SAD (not included in count) = 23

Includes:

- •500GB, 1h/ 1D Top and Bottom Depop Models
- •1-2-3D Native + 3D/4H Models
- Bacall Unique Items
- PCBA / Electrical

Recommendation – **Approve SAD**. Ongoing actions not gating CTU / critical to volume support in FQ4:

- Finalize Supply chain Qualifications on HU / PCCA / PCC in CRT2
- Complete 430SS MMI Ch Qual in Feb
- •Continue with post SAD qual staging on DDR shrink, TI Dillon, SIT Gateway and 1D / 1H evaluations on new actuator machining.

Page 100

© Seagate Confidential

Key Supply Chain Documents

SSP



AMLR to BOM



Ramp Readiness



ADR3 Document



CONFIDENTIAL

Back Up

CONFIDENTIAL

Product Summary Case 3:16-cv-00523-JCS Document 155-5 Filed 01/12/18 Page 104 of 128

Product	Highlight
GrenadaBP2	Ref. Config plan rev.41, No supply issue.
Crawford	Ref. Config plan rev63, Overall no HGA supply issue. On AB7/NB7 childlot (BL#433 & 474) HGA commit in WW29 & WW31 based on slider supply. Need LCO to adjust drive build based on materials readiness. On additional HSA BL#478,482,476,477 (520HSA) within materials lead time, HSA is able to support in WW33 based on PCC & ACA supply in late of Jan.
Angsana1DH	Ref. Config rev2.8, No issue.
Chengai1D	Ref. Config rev3.3, Gen1D has shipped 20HSA in WW27 & plan to 280HSA in WW28. Balance 100HSA plan to ship in WW29 due to late hook up supply.
Angsana2D	Ref. Config rev.6.5, No HGA supply issue.
Avenger	Ref. TCO Schedule 01/02. Gen 3 Builds: RHO allow to start build Gen 3 on 1/3. Expect to recover all in WW29.
Thunderbolt	Ref. TCO schedule 12/18. Gen3 HGA demand 0.9K in WW28 will use HGA passser from WQ build per RHO CT instruction. HGA plan to ship in WW29. The WQ testing is still pending for RHO CT to finalize ET TSR & specfication. Chkpt 01/09.
ValkyrieBP	Ref. TCO schedule 12/20
	- Fairlane look ahead HGA build is in progress and requires RHO CT review HGA data prior making shipment to Kaifa. So, HGA plans to ship 1.8K in WW29.
	- RDT HGA demand 30K in WW29 has been seperated to 22.4K PX5 wafer and 8.4K NL6 wafer. No issue to support 22.4K PX5 in WW29. On NL6 wafer, HGA will commit partial commit in WW30 & complete in WW31 based on wafer-slider supply. Need TCO to adjust drive build accordingly.
Makara	Ref. Config plan rev.85, Mat 6.0 for Teparuk HGA qualification has complered & shipped in WW27. TK : Gen2 Builds . RHO decided to stop MAT 6 HSA build 1 day due to Drive reli and CERT fails (Potentail to use wafer 2A to replace 9C). Checkpoint with RHO/LCO CT 1/9. MAT6 BL#380/376/382 H SA commits based on BIT Hook ups supply plan ETA 2/10. H SA to be built 2/11 (ww33). 6D NL rework qual/BL#600 qty 643 HSAs HSA need to re-build. Pending BIT HU new commit. Check point 1/9.

Media 3 Demand Supply 10 Delta 2003 144 MS

MS1407B0				_								Q3'14
Requirement (MS1407B0)	Plan											
Commit (MS1407B0)				Feb				Mar				
EOH (Cum Delta)	w28	w29	w30	w31	w32	w33	w34	w35	w36	w37	w38	w39
YarraBP	6	6	8	8	4	1	10	12	6	0	0	0
YarraR	157	123	171	166	67	27	15	163	324	498	566	502
Kahuna	247	282	230	250	356	207	44	26	101	173	237	256
Angsana	41	31	16	16	27	18	16	16	17	17	17	17
Angsana2D / 2DH / H	0	0	0	0	0	0	0	0	32	13	6	0
M8	1,188	663	678	983	953	474	667	506	336	721	930	1,224
M9T	29	1	24	303	353	474	461	570	679	669	569	469
F3	5	5	10	0	0	0	0	0	0	0	0	0
Pharaoh	290	274	383	200	101	326	428	428	579	521	379	536
Grenada	407	1,244	2,093	2,036	4.657	2,260	2,501	2,510	2,691	2,949	3,534	4,274
Hepburn	28	275	227	258	177	143	99	69	38	99	248	489
Bacall	146	95	157	73	17	73	101	157	213	269	353	431
Lombard	119	171	217	262	285	338	384	395	425	493	427	381
Crawford	0	0	0	0	20	18	16	8	1	2	3	9
MuskiePlus	0	25	49	32	8	27	0	0	0	0	0	0
Mantaray	0	0	0	0	0	0	0	0	0	0	0	0
Megalodon	1,992	1,753	1,45	1,433	1,480	1,676	1,755	1,689	1,382	1,150	>964	565
Makara	11	41	31	31	10	27	7	- 55	82	92	83	96
Eagle	36	262	317	266	204	256	249	268	244	244	233	286
Compass	3	3	3	3	3	3	3	3	3	3	3	3
Airwalker	294	267	267	181	154	181	207	303	341	394	447	400
Yellow Jacket	233	269	305	333	297	290	297	305	341	305	254	259
LightningBug	158	207	295	349	365	371	371	383	366	399	431	460
Valkyrie	0	0	0	0	0	0	0	0	0	2	2	1
Ironman	0	0	0	0	0	0	4	7	15	15	23	37
Avenger	0	0	0	0	0	0	0	0	0	0	0	0
Thunderbolt	0	0	0	0	0	0	0	0	0	0	0	0
TOTAL @ RMO	5,391	5,995	6,942	7,183	6,738	7,189	7,635	7,873	8,216	9,029	9,710	10,694
TOTAL @ RMO without M8/M9/F3	4,169	5,326	6,230	5,898	5,432	6,241	6,507	6,797	7,201	7,638	8,211	9,000

Grenada/Megalodon – Building more to cater for upside..

LB - 126k (Kao) FG on hold pending usage .. Approval WW30.

Media 3 Demand Supply 1 Detta 2004144 MS

MS1407B0														Q4'14
Requirement (MS1407	7B0)	Plan	Plan	Plan	Plan	Plan	Plan	Plan	Plan	Plan	Plan	Plan	Plan	Plan
Commit (MS1407B0)		Apr				May				Jun				
EOH (Cum Delta)	w39	w40	w41	w42	w43	w44	w45	w46	w47	w48	w49	w50	w51	w52
YarraBP	0	0	0	0	0	0	0	0	0	0	0	0	0	0
YarraR	502	447	382	313	253	72	314	348	401	126	161	197	140	62
Kahuna	256	140	189	243	233	259	125	183	237	137	190	174	186	190
Angsana	17	8	6	7	23	38	19	20	36	52	35	17	30	44
Angsana2D / 2DH / H	0	29	22	33	26	20	49	44	38	33	37	31	21	12
M8	1,224	1,351	1,478	1,555	1,632	1,709	1,786	1,863	1,790	1,717	1,644	1,596	1,548	1,755
M9T	469	560	651	742	833	924	915	906	897	888	879	860	696	532
F3	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Pharaoh	536	491	416	410	388	450	460	424	338	175	127	66	445	809
Grenada	4,274	4,125	3,907	3,714	3,629	3,506	3,383	3,244	3,033	2,846	2,658	2,422	2,327	2,511
Hepburn	489	435	384	345	272	230	189	148	180	228	311	253	261	330
Bacall	431	403	375	347	347	291	235	235	263	263	263	263	263	289
Lombard	381	315	300	273	201	268	274	280	286	308	354	304	306	307
Crawford	9	8	15	20	28	33	41	46	54	59	89	41	35	28
MuskiePlus	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Mantaray	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Megalodon	565	285	717	1,030	1,211	1,364	1,518	1,720	1,648	1,467	1,286	938	826	788
Makara	96	162	170	223	83	46	53	45	29	69	46	23	182	71
Eagle	286	217	238	218	209	294	362	370	360	368	370	269	217	285
Compass	3	3	3	3	3	3	3	3	3	3	3	3	3	3
Airwalker	400	398	453	498	454	445	436	438	424	429	434	368	387	401
Yellow Jacket	259	226	236	232	214	224	220	216	197	150	160	127	137	147
LightningBug	460	355	391	426	469	495	492	474	443	422	445	375	421	440
Valkyrie	1	11	24	35	46	57	67	77	72	68	69	45	23	1
Ironman.	37	23	36	32	37	65	65	79	72	79	107	82	81	81
Avenger	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Thunderbolt	0	0	0	0	0	0	0	0	0	0	0	25	0	0
TOTAL @ RMO	10,694	9,993	10,394	10,700	10,590	10,796	11,006	11,164	10,801	9,887	9,670	8,480	8,540	9,087
TOTAL @ RMO withou	9,000	8,081	8,264	8,402	8,125	8,162	8,304	8,395	8,114	7,282	7,147	6,023	6,295	6,800

Q3'14 HGSA supply status

MS1407B0		Já	an		Fe	eb				Mar			Issues / Actions
EOH (Cum delta)		ww29	ww30	ww31	ww32	ww33	ww34	ww35	ww36	ww37	ww38	ww39	
Pharaoh/Hepburn	HGA Native S8	195	38	816	1422	1406	1290	1313	1230	1098	2011	2086	
	HGA Native S7	193	(1)	271	363	313	267	301	239	145	469	640	No cumply issue with year tight HCA cumply in Jan
	HGA BTC S6	40	44	41	65	27	(14)	(58)	(84)	(104)	(79)	(67)	No supply issue with very tight HGA supply in Jan.
13wks MS1407A0	Total HGA	429	80	1127	1850	1746	1543	1557	1385	1140	2401	2660	
Pharaoh/Hepburn	HGA Native	(173)	(549)	477	1152	1062	651	460	66	(409)	578	827	Drive upside 1M; +280K/Jan, +3K/Feb, +723K/Mar (2M HGA).
	HGA BTC	(36)	(39)	(48)	(29)	(74)	(127)	(183)	(222)	(253)	(241)	(231)	HGA shortfalls in ww29-30 & ww36-37 (per max wafer/SLD due to
MS1407B0	Total HGA	(209)	(587)	430	1122	988	524	277	(156)	(663)	338	595	lead-time issue). Continue working on wafer/SLD improvement.
Grenada Summary	HGA Native S7	610	452	1324	1755	2037	1644	1617	2162	2556	2457	1992	
	HGA S6	(187)	(240)	(202)	(263)	(199)	(144)	(65)	(1)	89	84	72	Drive cut -0.5M (-2M HGA) - No supply issue.
MS1407B0	TTL HGA	423	212	1122	1493	1838	1500	1552	2162	2645	2541	2064	
YarraR	HGA	(175)	(175)	(133)									Drive cut 55K in Jan, maximize Wuxi build and fast truck Hook-up
	Hook up	(82)	(95)	(80)	(43)								shipments, this helps to reduce drive gap in Jan from 284K to 79K
MS1407B0	Drive		(79)	(79)	(79)	(60)							which will be able to recover in Feb No customer impact.

Q4'14 – No supply issue

Excess Material – WW29 Status

Scrap by Factory / Owner

Total Grenada / Bacall BP2 Factory & DC Excess Material = \$334k

- Korat TTL "on Hold" Material = \$311K
- •\$12k Plastic DSP from December Retail, Pending cleanliness resolution
- •\$299k slider / Wafer Qual Material RHO
- •Wuxi TTL "on Hold Material = \$12.5k
- •\$4.6k RHO, due to PZT conductivity failures
- \$7.9k all other materials
- •SZ TTL "on Hold" Material = \$10.1k
- •\$3.2k RHO, MPT issue
- •\$6.9k all other mechanical items
- •LCO DC = ~ \$50
- •WW29 Factory Excess Report below, Factory detail on following pages



Page 107

© Seagate Confidential

Scrap Detail WW29-JC Korat Filed 01/12/18 Page 109 of 128

Updated as of 13 Jan '14	On-Hold \$	On-Hold \$ Remarks			
HDAs level Inventory - Korat					
PLATE,SEPARATOR p/n: 707647900 cost \$0.75 & 0.9 (Good-1550+12000,Bad-0)	11963	Plastic DSP is being modified by LCO, this version may be unusable for Mass volume, holding it in UPS store and internal hub while waiting for disposition from Bob and LCO	Hold pending cleanliness methodology determination		
HGA Inventory @ Teparuk					
Slider wip (Good - Bad -130,478)	88725	Slider not ChunkM/8, SSO#NBSSO6121,NBSS06155	RHO Dispostion		
HGA wip (Good - 0, Bad - 130,846 209877	HGA excess from WQ & Evalaution	Required			
(Korat) Total Grenada BP2 Cost	\$310,565				

Scrap Detaile WW29-JCWX cument 155-5 Filed 01/12/18 Page 110 of 128

Grenada BP2 Overall Inventory Costs (Sliders, HGSAs, Media, Drives)

Current Phase Status: GEN1, GEN 2

Current Fridse Status: GEN1, GEN 2			
Updated as of 13 Jan '14	On-Hold \$	Remarks	Status
HDAs level Inventory - Wuxi			
Media,PN:100728039,RMO G9LT Aperio,Qty wip:292pcs prime;12pcs recycle	48		
Media,PN:100715596,FG9LT,16D, 8.5k, LIM. wip 267pcs prime;238pcs scrap	942	Will RTV in Jan	
Media,PN:100731321,G10.5+,wip 10pcs recycle	40		
MBA,PN:100733087, Qty wip:5pcs prime; Opcs recycle	24	NTC PN inventory	Scrap to
MBA,PN:100738739,qty wip 22pcs recycle	108	line fail from WUBGD41147A	70038
MBA,PN:100739347,qty wip 8pcs recycle;60pcs prime	33	line fail from WX131125B14BRHE	
Cover,PN:100722115,Qty wip:24pcs recycle;0pcs prime	21	line fail from WUBGD21146A	
Cover,PN:100722116,Qty wip:28pcs recycle;0pcs prime	25	recycle from WUGGD4C0003	
HSA Inventory @Wuxi			
P/N:100725134(Good Wip:368pcs)	4577	non-POR HSA from SBR#BP2K058 demand cancel	Scrap to 70038
P/N:100738495(Bad Wip:365pcs)	4632	T/D from CRT1 HAS affected MPT PZT conductivity exposure issue	Scrap to RHO
P/N:100728636(Good Wip:38pcs)	482	non-POR HSA from PVT4	Factory Scrap
P/N:100738493(Bad Wip:44pcs)	376	Wuxi Scrap HAS from line fail	•
P/N:100738495(Bad Wip:8pcs)	102	Wuxi Scrap HAS from line fail	RTN for
P/N:100738496(Bad Wip:32pcs)	548	Wuxi Scrap HAS from line fail	Teardown
P/N:100738498(Bad Wip:16pcs)	274	Wuxi Scrap HAS from line fail	and reclaim
P/N:100738499(Bad Wip:21pcs)	266	Wuxi Scrap HAS from line fail	
PCBA Inventory			
	THE COURSE COMME CONTRACT COMME		

(Wuxi) Total Grenada BP2 Cost \$12,519

Page 109

© Seagate Confidential

Scrap Detail WW29-JCSZ Pocument 155-5 Filed 01/12/18 Page 111 of 128


Grenada BP2 Overall Inventory Costs (Sliders, HGSAs, Media, Drives)			
Current Phase Status: GEN1, GEN 2			
Updated as of 13 Jan '14	On-Hold \$	Remarks	Status
HDAs level Inventory - Suzhou			
Cover,PN:100722117,Qty wip:90pcs recycle;0pcs prime	131		
Media,PN:100734184,Qty wip:452pcs recycle;	1789	line fail from Bacall BBP2 CRT 1.0 1D1 / RHO / TI	
Media,PN:100715596,Qty wip:18pcs recycle;	71	line fail from Bacall BBP2 CRT 1.0 1D1 / RHO / TI	Scrap to 70038
Media,PN:100731321,Qty wip:24pcs recycle;	95	line fail from Bacall BBP2 CRT 2 1D2 / TDK / LSI	
HSA Inventory @Suzhou			
P/N:100725132(bad Wip: 0pcs recycle;332pcs prime)	2836	Excess HGSA due to demand reduced,non- POR Pn,suggest to scrap	Scrap to 70038
P/N:100738493 (bad wip:380pcs recycle)	3246	MPT issue ,Need scrap	RHO Scrap
P/N:100728716 (bad wip:62pcs recycle)	530	line fail	Rework /
P/N:100738497 (bad wip:19pcs recycle)	17	line fail	Scrap non
P/N:100728717 (bad wip:16pcs recycle)	137	line fail	usable
P/N:100728719 (bad wip:35pcs recycle)	139	line fail	components
P/N:100738495 (bad wip:4pcs recycle)	49	line fail	components
PCBA Inventory			
PN:100723921, 40pcs recycle	305	GBP31 PCBA inventory	Scrap authorized previously
Drives AFGI-T			
H.DA,123pcs fail	759	Fail H.DA of Grenada MMI China 430 TC Qual Builds/SBS / Disty CDU / 3TB/Grenada Option 3 Qual Builds	Pending Disposition
(Suzhou) Total Grenada BP2 Cost	\$10,103		

Page 110

© Seagate Confidential

GRENADABP2 - 01/08/2014

Summary of Gen 2



4-Corner

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
Thermal Voltage Margins: (TVM)	Υ	1-0-31	6-0-30	13-0-240	0-0-28
Thermal Voltage Margins - NL: (TVM_NL)	N				

Acoustics

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
Acoustic APM: (ACAPM)	N				
Acoustic Latch - Power off Retract: (ALPOR)	Y	0-0-30	0-0-10	0-0-10	
Acoustic LUL: (ACLUL)	Υ				
Acoustic Sound Power: (ASPWR)	Υ	0-0-120	0-0-40	0-0-40	
CE Sound Quality: (CESQ)	N				
PDT Prominence Ratio: (PDT_PR)	Y				

Cranada DD3 Can3 DNAT

Agency

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
DC Magnet Test: (DCMAG)	N				
ElectroMagnetic Compatibility: (EMC)	Y				0-0-12 09/17/2013 S
Electro-Static Discharge-Non Operating: (ESD_NOP)	Y	0-0-6	0-0-2	0-0-2	0-0-2
Electro-Static Discharge-Operating: (ESD)	N				
Magnetic Fratricide: (MAGFrat)	Y				
Mobile Device Immunity, Drive Level: (MDID)	N	******			
Mobile Device Immunity, System Level: (MDIS)	N				
Non-Operating Uniform Stray Field Test 2.5 Inch: (NOMAG_UF)	N				
Radiated Emission: (RadEm)	N	0-0-3	0-0-1	0-0-1	0-0-1
Safety Certification: (SCert)	Υ				0-0-8 08/27/2013 S

Baseline

Test Name	SBS	500 GB	1000 GB	2000 GB	3000 GB
Baseline (ODT) - interface: (BL_ODT_I)	N	0-1-278 * 09/23/2013 S	1-0-113	2-1-858	0-0-119

Grenada BP2 Gen2 DMT

Environmental Stress

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
Accelerated Storage Test 60C/80RH: (ASTL1)	Υ	1-0-33	0-0-11	0-0-11	
Accelerated Storage Test 70C/75RH: (ASTL2)	N				
Accelerated Storage Test 85C/85RH: (ASTL3)	N				
Cold Contamination Test: (CCTst)	N	0-0-30	0-0-11	0-0-11	0-0-11
Hot Storage Test: (HST)	Υ	0-0-30	0-0-10	0-0-10	0-0-10
Rapid Humidity Acclimation Test: (RHAT)	N	0-0-30	0-0-82	0-0-10	0-0-10
Seagate Environmental Stress Test: (SEST)	Υ				
Transit Storage Environment: (TSE)	N				

Head/Media Interface

Test Name	SBS	500 GB	1000 GB	2000 GB	3000 GB
Accelerated Burnish Test: (ABT)	Υ	0-0-91	0-0-30	0-0-30	
Adjacent TrackInterferance Nearline: (ATI_NL)	N				
Adjacent Track Interferance Nearline - Margin Test: (ATI_NL_M)	N			:	
Adjacent Track Interference: (ATI)	N				
Altitude: (ALT)	Υ	1-0-15	0-0-5	0-0-5	
Altitude Flyability: (Alt Fly)		0-0-12	0-0-4	0-0-4	
Ambient LUL - Hard: (ALULH)	N	0-0-30	1-0-10	0-0-10	
Ambient LUL - Soft: (ALULS)	N	1-0-31	0-0-10	0-0-10	
Extended ATI: (XATI)	N				
Full Stroke Seek: (FSS)	N				
On Track Dwell: (OTD)	N				
Stress LUL - Hard 32 80: (SLULH32_80)	N	0-0-15	0-0-5	0-0-5	0-0-5
Stress LUL - Hard 5 20: (SLULH5_20)	N	0-0-25	0-0-5	0-0-5	
Stress LUL - Hard 60 20: (SLULH60_20)	N	0-0-15	0-0-5	0-0-5	
Stress LUL - Soft 32 80: (SLULS32_80)	N	0-0-15	0-0-5	0-0-5	
Stress LUL - Soft 5 20: (SLULS5_20)	N	0-0-15	0-0-5	0-0-5	
Stress LUL - Soft 60 20: (SLULS60_20)	N	0-0-15	0-0-5	0-0-5	-
Thermal Decay: (TDEC)	N				

Grenada BP2 Gen2 DMT

Power/Electrical

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
DC Current and Power Consumption: (DCPwr)		0-0-15	0-0-5	0-0-5	
DC Ripple and Conducted Noise: (DCRip)	Υ	0-0-15	0-0-5	0-0-5	
Hot Plug: (HotPlg)	N				
PCBA Thermal Map: (PCBATM)	Y	0-0-6 09/25/2013 S	0-0-2 09/25/2013 S	0-0-2 09/25/2013 S	
Power Consumption: (PWR_CON)	Υ				
Power Loss Recovery: (PLR)	Υ	0-0-15	0-0-5	0-0-5	
Power Supply Ramping: (PSR)	Υ	0-0-15	0-0-5	0-0-5	
Start and Stop Timing: (SST)	Y	0-0-15	0-0-5	0-0-5	

Cranada DD2 Can2 DNAT

Shock and Vibration

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
Baseplate Distortion: (BSPLDIS)	N				
Non-Operating Shock - Rotary: (RNOS)	N				·
Non-Operating Shock One Axis Fragility (1 msec): (NOS1A_1)	Y				
Non-Operating Shock One Axis Fragility (1/2 msec): (NOS1A_H)	Y	-			
Non-Operating Shock One Axis Fragility (11 msec): (NOS1A-11)	N				
Non-Operating Shock One Axis Fragility (2 msec): (NOS1A_2)	Y				
Non-Operating Shock Six Axis (.5msec): (NOS6A_05)	Y	0-0-9	0-0-3	0-0-3	0-0-3
Non-Operating Shock Six Axis (11 msec Lenovo): (NONOS_11LEN)	N				
Non-Operating Shock Six Axis (11ms): (NOS6A_11)	N				
Non-Operating Shock Six Axis (1msec): (NOS6A_1)	Y	0-0-9	0-0-3	0-0-3	0-0-3
Non-Operating Shock Six Axis (2msec): (NOS6A)	Y	0-0-9	0-0-3	0-0-3	0-0-3
Non-Operating Vibration - Random: (NOVR)	Y				
Non-Operating Vibration - Sine: (NOVS)	Y				
Operating Shock - Rotary: (ROS)	N				
Operating Shock (11ms): (OS_11)	N				^
Operating Shock (2ms): (OS_2)		0-0-18	0-0-6	0-0-6	0-0-6
Operating shock six axis 0.5ms: (OS6_HALF)	Y				
Operating Shock Six Axis 1ms: (OS6_1)	Y				
Operating Shock Six Axis 2 ms: (OS6_2)	Y				
Operating Vibration - Linear Random: (LROV)	Y	0-0-9	0-0-3	0-0-3	0-0-3
Operating Vibration - Random: (OVR)	Y				
Operating Vibration - Rotary Random: (RROV)	Y	0-0-9	0-0-3	0-0-3	0-0-3
Operating Vibration - Sine: (OVS)	Y				
Table Drop Test: (TBL_DP)	N				
Top Cover Stiffness Test: (TCST)	Y				
Topple Drop: (TD)	Y	0-0-15	0-0-5	0-0-5	0-0-5

Grenada BP2 CRT 1.0 DMT


Baseline

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
Baseline (ODT) - interface: (BL_ODT_I)	N	0-0-252 11/23/2013	0-0-118	0-0-144	0-0-162

Environmental Stress

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
Accelerated Storage Test 60C/80RH: (ASTL1)	Υ			0-0-7 01/04/2014	0-0-9 01/04/2014
Accelerated Storage Test 70C/75RH: (ASTL2)	N				
Accelerated Storage Test 85C/85RH: (ASTL3)	N				
Cold Contamination Test: (CCTst)	N				
Hot Storage Test: (HST)	Υ				
Rapid Humidity Acclimation Test: (RHAT)	N				
Seagate Environmental Stress Test: (SEST)	Υ				
Transit Storage Environment: (TSE)	N	******	******		

TestName	SBS	500 GB	1000 GB	2000 GB	3000 GB
Baseplate Distortion: (BSPLDIS)	N				
Non-Operating Shock - Rotary: (RNOS)	N				
Non-Operating Shock One Axis Fragility (1 msec): (NOS1A_1)	Y				
Non-Operating Shock One Axis Fragility (1/2 msec): (NOS1A_H)	Y				
Non-Operating Shock One Axis Fragility (11 msec): (NOS1A-11)	N				
Non-Operating Shock One Axis Fragility (2 msec): (NOS1A_2)	Y	<u></u>			
Non-Operating Shock Six Axis (.5msec): (NOS6A_05)	Y	0-0-6 11/15/2013 S	0-0-3 11/15/2013 S	0-0-6 11/15/2013 S	0-0-6 11/18/2013 S
Non-Operating Shock Six Axis (11 msec Lenovo): (NONOS_11LEN)	N				
Non-Operating Shock Six Axis (11ms): (NOS6A_11)	N				
Non-Operating Shock Six Axis (1msec): (NOS6A_1)	Y	0-0-6 11/16/2013 S	0-0-3 11/16/2013 S	0-0-6 11/16/2013 S	0-0-6 11/19/2013 S
Non-Operating Shock Six Axis (2msec): (NOS6A)	Y	0-0-6 11/15/2013 S	0-0-3 11/15/2013 S	0-0-6 11/15/2013 S	0-0-6 11/18/2013 S
Non-Operating Vibration - Random: (NOVR)	Y		100 to 100 to		
Non-Operating Vibration - Sine: (NOVS)	Y				
Operating Shock - Rotary: (ROS)	N				
Operating Shock (11ms): (OS_11)	N				
Operating Shock Read Six Axis (2ms): (OSR6A_2)		0-0-6 11/26/2013 S	0-0-3 11/26/2013 S	0-0-6 11/26/2013 S	0-0-6 11/29/2013 S
Operating shock six axis 0.5ms: (OS6_HALF)	Y				
Operating Shock Six Axis 1ms: (OS6_1)	Y				
Operating Shock Six Axis 2 ms: (OS6_2)	Y				
Operating Shock Write Six Axis (2ms): (OSW6A_2)		0-0-6 11/26/2013 S	0-0-3 11/26/2013 S	0-0-6 11/26/2013 S	0-0-6 11/29/2013 S
Operating Vibration - Linear Random: (LROV)	Y			0-0-3 11/14/2013 S	
Operating Vibration - Random: (OVR)	Y				
Operating Vibration - Rotary Random: (RROV)	Y				
Operating Vibration - Sine: (OVS)	Y				
Table Drop Test: (TBL_DP)	N				
Top Cover Stiffness Test: (TCST)	Y				
Topple Drop: (TD)	Y	0-0-10	0-0-10	0-0-15	1-0-10 12/05/2013



Racall RD2 Gan2 DN/T

Agency

TestName	SBS	1000 GB	2000 GB
DC Magnet Test: (DCMAG)	N		
ElectroMagnetic Compatibility: (EMC)	Υ		
Electro-Static Discharge-Non Operating: (ESD_NOP)	Y	0-0-4	0-0-2
Electro-Static Discharge-Operating: (ESD)	N		
Magnetic Fratricide: (MAGFrat)	Y		
Mobile Device Immunity, Drive Level: (MDID)	N		
Mobile Device Immunity, System Level: (MDIS)	N		
Non-Operating Uniform Stray Field Test 2.5 Inch: (NOMAG_UF)	N		
Radiated Emission: (RadEm)	N	0-0-2	0-0-1
Safety Certification: (SCert)	Υ		,

Baseline

TestName	SBS	1000 GB	2000 GB
Baseline (ODT) - interface: (BL_ODT_I)	N		

Bacall BP2 Gen2 DMT

Environmental Stress

TestName	SBS	1000 GB	2000 GB
Accelerated Storage Test 60C/80RH: (ASTL1)	Υ	0-0-22	0-0-19
Accelerated Storage Test 70C/75RH: (ASTL2)	N		
Accelerated Storage Test 85C/85RH: (ASTL3)	N		
Cold Contamination Test: (CCTst)	N	0-0-22	0-0-22
Hot Storage Test: (HST)	Υ	0-0-21	0-0-21
Rapid Humidity Acclimation Test: (RHAT)	N	0-0-20	0-0-20
Seagate Environmental Stress Test: (SEST)	Υ		
Transit Storage Environment: (TSE)	N	0-0-12	0-0-6


Head/Media Interface

TestName	SBS	1000 GB	2000 GB
Accelerated Burnish Test: (ABT)	Υ	1-0-65	3-0-35
Adjacent TrackInterferance Nearline: (ATI_NL)	N		
Adjacent Track Interferance Nearline - Margin Test: (ATI_NL_M)	N		
Adjacent Track Interference: (ATI)	N		
Altitude: (ALT)	Υ	0-0-10	0-0-5 09/14/2013
AmbientLUL - Hard: (ALULH)	N	0-0-20	0-0-21
Ambient LUL - Soft: (ALULS)	N	0-0-20	0-0-20
Extended ATI: (XATI)	N		
Full Stroke Seek: (FSS)	N		
On Track Dwell: (OTD)	N		
Stress LUL - Hard 32 80: (SLULH32_80)	N		
Stress LUL - Hard 5 20: (SLULH5_20)	N		
Stress LUL - Hard 60 20: (SLULH60_20)	N		
Stress LUL - Soft 32 80: (SLULS32_80)	N	0-0-10	0-0-5
Stress LUL - Soft 5 20: (SLULS5_20)	N	0-0-10	0-0-5
Stress LUL - Soft 60 20: (SLULS60_20)	N	0-0-10	0-0-5
Thermal Decay: (TDEC)	N		

Bacall BP2 Gen2 DMT

Test Name	SBS	1000 GB	2000 GB
DC Current and Power Consumption: (DCPwr)		0-0-10	0-0-5
DC Ripple and Conducted Noise: (DCRip)	Y	0-0-10	0-0-5
Hot Plug: (HotPlg)	N		
PCBA Thermal Map: (PCBATM)	Y		
Power Consumption: (PWR_CON)	Y		
Power Loss Recovery: (PLR)	Y	0-0-10	0-0-5
Power Supply Ramping: (PSR)	Y	0-0-10	0-0-5
Start and Stop Timing: (SST)	Y	0-0-10	0-0-5

TestName	SBS	1000 GB	2000 GB
Baseplate Distortion: (BSPLDIS)	N	-	
Non-Operating Shock - Rotary: (RNOS)	N		
Non-Operating Shock One Axis Fragility (1 msec): (NOS1A_1)	Y		
Non-Operating Shock One Axis Fragility (1/2 msec): (NOS1A_H)	Y		
Non-Operating Shock One Axis Fragility (11 msec): (NOS1A-11)	N		
Non-Operating Shock One Axis Fragility (2 msec): (NOS1A_2)	Y		
Non-Operating Shock Six Axis (.5msec): (NOS6A_05)	Y		
Non-Operating Shock Six Axis (11 msec Lenovo): (NONOS_11LEN)	N		
Non-Operating Shock Six Axis (11ms): (NOS6A_11)	N		
Non-Operating Shock Six Axis (1msec): (NOS6A_1)	Y		
Non-Operating Shock Six Axis (2msec): (NOS6A)	Y	0-0-12	0-0-6
Non-Operating Vibration - Random: (NOVR)	Y		
Non-Operating Vibration - Sine: (NOVS)	Y		
Operating Shock - Rotary: (ROS)	N		
Operating Shock (11ms): (OS_11)	N		
Operating Shock (2ms): (OS_2)		0-0-12	0-0-6 08/20/2013 S
Operating shock six axis 0.5ms: (OS6_HALF)	Y		
Operating Shock Six Axis 1ms: (OS6_1)	Y		
Operating Shock Six Axis 2 ms: (OS6_2)	Y		
Operating Vibration - Linear Random: (LROV)	Y	0-0-6	0-0-3
Operating Vibration - Random: (OVR)	Y	0-0-6	0-0-3
Operating Vibration - Rotary Random: (RROV)	Y	0-0-6	0-0-3
Operating Vibration - Sine: (OVS)	Y	0-0-6	0-0-3
Table Drop Test: (TBL_DP)	N		
Top Cover Stiffness Test: (TCST)	Y		
Topple Drop: (TD)	Y	0-0-10	0-0-5



Bacall BP2 CRT 1.0 DMT

Baseline

TestName	SBS	1000 GB	2000 GB	3000 GB
Baseline (ODT) - interface: (BL_ODT_I)	N	0-0-258	1-1-173 11/26/2013	5-4-774

Environmental Stress

TestName	SBS	1000 GB	2000 GB	3000 GB
Accelerated Storage Test 60C/80RH: (ASTL1)	Υ			0-0-22 12/27/2013
Accelerated Storage Test 70C/75RH: (ASTL2)	N			
Accelerated Storage Test 85C/85RH: (ASTL3)	N			
Cold Contamination Test: (CCTst)	N			
Hot Storage Test: (HST)	Υ			
Rapid Humidity Acclimation Test: (RHAT)	N			
Seagate Environmental Stress Test: (SEST)	Υ			
Transit Storage Environment: (TSE)	N			

TestName	SBS	1000 GB	2000 GB	3000 GB
Baseplate Distortion: (BSPLDIS)	N			
Non-Operating Shock - Rotary: (RNOS)	N			
Non-Operating Shock One Axis Fragility (1 msec): (NOS1A_1)	Y			
Non-Operating Shock One Axis Fragility (1/2 msec): (NOS1A_H)	Y			
Non-Operating Shock One Axis Fragility (11 msec): (NOS1A-11)	N			
Non-Operating Shock One Axis Fragility (2 msec): (NOS1A_2)	Y			
Non-Operating Shock Six Axis (.5msec): (NOS6A_05)	Y	0-0-3 11/17/2013 S	0-0-3 11/17/2013 S	0-0-9 11/17/2013 S
Non-Operating Shock Six Axis (11 msec Lenovo): (NONOS_11LEN)	N			
Non-Operating Shock Six Axis (11ms): (NOS6A_11)	N			
Non-Operating Shock Six Axis (1msec): (NOS6A_1)	Y	0-0-3 11/18/2013 S	0-0-3 11/18/2013 S	0-0-9 11/18/2013 S
Non-Operating Shock Six Axis (2msec): (NOS6A)	Y	0-0-3 11/17/2013 S	0-0-8 12/05/2013 S	0-0-16 11/17/2013 S
Non-Operating Vibration - Random: (NOVR)	Y			
Non-Operating Vibration - Sine: (NOVS)	Y			
Operating Shock - Rotary: (ROS)	N			
Operating Shock (11ms): (OS_11)	N			
Operating Shock Read Six Axis (2ms): (OSR6A_2)		0-0-3 11/28/2013 S	0-0-3 11/28/2013 S	0-0-9 11/28/2013 S
Operating shock six axis 0.5ms: (OS6_HALF)	Y			
Operating Shock Six Axis 1ms: (OS6_1)	Y			
Operating Shock Six Axis 2 ms: (OS6_2)	Y			
Operating Shock Write Six Axis (2ms): (OSW6A_2)		0-0-3 11/28/2013 S	0-0-3 11/28/2013 S	0-0-9 11/28/2013 S
Operating Vibration - Linear Random: (LROV)	Y	0-0-3 11/16/2013 S	0-0-3 11/16/2013 S	0-0-9 11/16/2013 S
Operating Vibration - Random: (OVR)	Y	0-0-3 11/15/2013 S	0-0-3 11/15/2013 S	0-0-9 11/15/2013 S
Operating Vibration - Rotary Random: (RROV)	Y	0-0-3 11/15/2013 S	0-0-3 11/15/2013 S	0-0-9 11/15/2013 S
Operating Vibration - Sine: (OVS)	Y	0-0-3 11/15/2013 S	0-0-3 11/15/2013 S	0-0-9 11/15/2013 S
Table Drop Test: (TBL_DP)	N			
Top Cover Stiffness Test: (TCST)	Y			
Topple Drop: (TD)	Y	2-0-10 11/16/2013 S	0-0-15	9-0-25